
SZS ENGINEERING ACCESS

3156 REDWOOD DRIVE

ADA ACCESS COMPLIANCE ASSESSMENT

3156 REDWOOD DRIVE, REDWAY CA (COUNTY LEASED FACILITY)





Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Email: Info@szs.engineering

Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200 Palo Alto CA 94303 Tel: 866.694.7637 www.szs.engineering

March 8, 2019



Humboldt County Administrative Office Management and Budget Team 825 Fifth Street, Room 112 Eureka, California 95501 Attention: Chris Shaver, Asst. CAO

Re: 3156 REDWOOD DRIVE - ADA ACCESS COMPLIANCE ASSESSMENT

Dear Mr. Shaver,

We are pleased to submit this report as a first step in the process to identify barriers to access for the County of Humboldt. This process will allow the County to apply programmatic accessibility before resorting to physical barrier removal, in order to conserve funds while meeting the goal of improving access.

This has been an informative process. We look forward to creating an updated digital remediation program to facilitate implementation. Please review the report and provide input. We welcome collaboration in this process.

Contact me with any questions you may have.

Regards,

Syroun Z. Sanossian, Principal

Syn 2. Emi

SZS Engineering Access, Inc.



TABLE OF CONTENTS

1.	EXEC	UTI	VE SUMMARY	p. 1
		A.	Private Entities, Public Accommodations and the ADA	p. 3
		В.	Safe Harbor Provisions	p. 7
		C.	Barrier Severity Ratings and Remediation	p. 8
		D.	Official Responsible	p. 9
		E.	Recommended Barrier Removal Priorities	p. 9
		F.	Cost Estimates	p. 11
		G.	Exterior Spaces	p. 11
		н.	Facility Entrances	p. 12
		i.	Report Format Definitions	p. 13
2.	EXTEI	RIOI	R SPACES	p. 16
3.	INTER	IOR	RSPACES	p. 16
4.	BARR	IER	DATA RECORDS	
	×	A.	Barrier Data Records	p. 17
		В.	Cost Estimate	p. 31



1. EXECUTIVE SUMMARY

This ADA Access Compliance Assessment was compiled for the facility located at 3156 Redwood Drive, which is intended to serve as a planning and building inspection satellite office for South Humboldt County. This structure may be leased by the County of Humboldt as a location where the County can provide county programs, services and activities. As a privately owned facility in which public activities take place, the facility is defined under the ADA as a public accommodation.

This report was developed to fulfill requirements under the consent decree entered into by the County of Humboldt with the US Department of Justice (DOJ). The United States alleged that Humboldt County has discriminated, and continues to discriminate, against individuals with disabilities by failing to make County facilities, programs, services, and activities accessible to and useable by individuals with disabilities in violation of the ADA.

The DOJ initiated a compliance review of Humboldt County under its Project Civic Access ("PCA") initiative, a wide-ranging effort to ensure that cities, counties, and other public entities throughout the country comply with the ADA by eliminating physical, communication, and other barriers that prevent people with disabilities from participating fully in community life. The DOJ's review of the County included a review of its programs and an accessibility survey of over 50 facilities, although the consent decree governs all facilities in which County programs, services or activities take place¹. As the result of its review, the Department found numerous violations of the ADA, notified the County of the violations and negotiated a settlement agreement in which the County committed to bring its facilities, programs, services and activities into compliance with the ADA.

SZS Engineering Access, Inc. is the Independent Licensed Architect ("ILA"), pre-approved by the DOJ, acting independently to certify whether any alterations, additions, or modifications made by the County during the term of this Consent Decree comply with the applicable standard pursuant to 28 C.F.R. § 35.151(c) and the Appendix to 28 C.F.R. § 35.151(c)².

In issuing certifications pursuant to this Consent Decree, the ILA will impartially prepare reports identifying each violation and demonstrating with photographs each violation that has been remediated. The ILA is considered a neutral inspector for purposes of issuing certifications of compliance.

Under the consent decree, the County agreed not to deny the benefits of its programs, services, and activities³ or discriminate against individuals with a disability, and will not, based on disability provide an unequal, different, or separate opportunity to participate in its programs, services, and activities⁴.

The intent of this assessment report is to identify physical barriers to access, so that design professionals can use the information to ensure that alterations to facilities that house County programs, services and activities result in facilities that are accessible to and usable by people with disabilities. This facility is owned by a private party. Where the owner leases the facility for use as a public accommodation, the facility must comply with requirements to provide access

US v. County of Humboldt, US v. County of Humboldt, Civil Action No. 16-5139, Attachment - G, H, I, J

² 28 C.F.R. § 35,151(c) and the Appendix to 28 C.F.R. § 35.151(c)

³ 28 C.F.R. § 35.130(b)(1).

^{+ 28} C.F.R. § 35.130(b)(1), (3).



to a public accommodation. If the County were to vacate this facility, the requirements will remain in place for any other parties leasing the facility that provide public accommodations.

The field investigation began on February 28, 2019. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions for the process of cost estimating. Digital photographs are provided within this report for each barrier to access to facilitate the review of the data collected. Technical data can be interpreted more efficiently with a visual component; the photos provide a clear connection between the technical data described in each barrier data record and the physical barrier to access identified.

When taking measurements in exterior areas, visual markers are used to indicate the location or beginning and end of a barrier such as a cross slope. Red cups or the digital level used to take measurements will be used in photos as a visual marker to indicate the location of these exterior barriers within the context of the existing site conditions.

This facility is located in a structure that was built before the enforcement of the Americans with Disabilities Act and barriers to access were identified.

ADA Title III holds that no individual shall be discriminated against on the basis of disability in the full and equal enjoyment of the goods, services, facilities, privileges, advantages, or accommodations of any place of public accommodation by any private entity who owns, leases (or leases to), or operates a place of public accommodation. The findings presented are both narrative and technical in nature. Physical barriers to access identified during the field investigation process are documented in two ways:

- 1. <u>Summary and Analysis</u>: An analysis of findings is provided in a narrative form that describes particular barriers identified in the following records to help ensure that the findings for atypical situations can be further explained. The intent of this information is to provide a discussion on the functionality of physical elements. Background reasoning and research behind the identification of barriers is also provided where universal design principles may play a role. This analysis may be accompanied by digital photographs or diagrams, where applicable. Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.
- 2. <u>Barrier Data Records:</u> Individual barriers to access are entered into the ADA/Access Compliance database so that technical information on each individual barrier can be provided a barrier data record. These barrier data records include detailed information including digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal will be assigned in the final report. The information is formatted with two barriers on each report page.

Each barrier identified in this report is designated as either required for removal or recommended for removal. State and federal model code provide the basis for most of the barrier identification contained in this report. There are other barriers to access that are dictated by case law precedent, vehicle code, health code, safety code and labor code. Most barriers identified in this report are based on those requirements but additional barriers exist



that are not based on these regulations or statutes. Barriers that are recommended for removal are based on pending regulations or good practices. The associated field provides two options for each barrier: Required or Recommended.

It is important to note that the barriers identified in this report reflect the most stringent requirements from the 2010 ADA Standards, California Code of Regulations/Title 24 and the California edition of the Manual on Uniform Traffic Control Devices (MUTCD). These model codes are not identical and contain conflicting requirements. To ensure ADA Access Compliance is achieved, this report is based on the most stringent requirements taken from these model codes.

In order to consolidate the barrier data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found. For instance, this occurs where barriers were identified in stairways that have existing handrails that continue through multiple floors.

A. PRIVATE ENTITIES, PUBLIC ACCOMMODATIONS AND THE ADA

The landmark Americans with Disabilities Act (ADA), enacted on July 26, 1990 provides comprehensive civil rights protection to individuals with disabilities in the many areas including employment, telecommunications, facilities that offer public accommodations, and state and local governmental services. The ADA is comprised of five parts, or titles. Each title covers a specific area delineated by the ADA, in which the legislation is intended to enhance accessibility for persons with disabilities. The five titles are as follows:

<u>Title I:</u> Employment Practices by units of State and Local Governments

Title II: Programs, Services and Activities of State and Local Governments

<u>Title III:</u> Public Accommodations and Commercial Facilities (private businesses and non-profit service providers)

Title IV: Telecommunications

Title V: Miscellaneous Provisions

Title III of the Americans with Disabilities Act of 1990 (42 U.S.C. 12181) applies to this property. Title III prohibits discrimination on the basis of disability by public accommodations and requires places of public accommodation and commercial facilities to be designed, constructed, and altered in compliance with the construction-related accessibility standards established by Section 36.101 of the Act. The 2010 ADA Standards have updated the original ADA as of March 2012.

Furthermore, ADA Title III holds that no individual shall be discriminated against on the basis of disability in the full and equal enjoyment of the goods, services, facilities, privileges, advantages, or accommodations of any place of public accommodation by any private entity who owns, leases (or leases to), or operates a place of public accommodation. Both the landlord who owns the site that houses a place of public accommodation and the tenant who owns or operates the place of public accommodation are responsible to provide accessible public accommodations subject to the requirements of this Title. As between the parties, allocation of



responsibility for complying with the obligations of this part may be determined by lease or other contract.⁵ The terms of the lease should define the responsibilities.

ACTIVITIES

Public accommodations also cannot deny participation to persons with disabilities, or provide for unequal or separate benefits for persons with disabilities. The basis of the ADA is the integration of persons with disabilities into society, not the expectation of preference or any type of special treatment.

A public accommodation shall afford goods, services, facilities, privileges, advantages, and accommodations to an individual with a disability in the most integrated setting appropriate to the needs of the individual. The maintenance of accessible features is essential. A public accommodation shall maintain in operable working condition those features of facilities and equipment that are required to be readily accessible to and usable by persons with disabilities by the Act, although this Act or section does not prohibit isolated or temporary interruptions in service or access due to maintenance or repairs.

ELIGIBILITY CRITERIA

A public accommodation shall not impose or apply eligibility criteria that screen out or tend to screen out an individual with a disability or any class of individuals with disabilities from fully and equally enjoying any goods, services, facilities, privileges, advantages, or accommodations, unless such criteria can be shown to be necessary for the provision of the goods, services, facilities, privileges, advantages, or accommodations being offered. But, a public accommodation may impose legitimate safety requirements that are necessary for safe operation. Safety requirements must be based on actual risks and not on mere speculation, stereotypes, or generalizations about individuals with disabilities. A public accommodation also may not impose a surcharge on a particular individual with a disability or any group of individuals with disabilities to cover the costs of measures, such as the provision of auxiliary aids, barrier removal, alternatives to barrier removal, and reasonable modifications in policies, practices, or procedures, that are required to provide that individual or group with the nondiscriminatory treatment required by the Act or this section.

MODIFICATIONS IN POLICIES, PRACTICES OR PROCEDURES

A public accommodation shall make reasonable modifications in policies, practices, or procedures, when the modifications are necessary to afford goods, services, facilities, privileges, advantages, or accommodations to individuals with disabilities, unless the public accommodation can demonstrate that making the modifications would fundamentally alter the nature of the goods, services, facilities, privileges, advantages, or accommodations. This is significant in terms of physical alterations made to improve accessibility for persons with disabilities. A public accommodation may refer an individual with a disability to another public accommodation, if that individual is seeking, or requires, treatment or services outside of the referring public accommodation's area of specialization, and if, in the normal

-

⁵ Department of Justice ADA Title III Regulations 28 CFR Part 36; Sec.36.105 -- 36.199 [Reserved] Subpart B -- General Requirements Sec.36.201 General. (b)



course of its operations, the referring public accommodation would make a similar referral for an individual without a disability who seeks or requires the same treatment or services.

AUXILIARY AIDS AND SERVICES

A public accommodation shall take steps that may be necessary to ensure that no individual with a disability is excluded, denied services, segregated or otherwise treated differently than other individuals because of the absence of auxiliary aids and services, unless the public accommodation can demonstrate that taking those steps would fundamentally alter the nature of the goods, services, facilities, privileges, advantages, or accommodations being offered or would result in an undue burden, i.e., significant difficulty or expense.

REMOVAL OF BARRIERS

A public accommodation shall remove architectural barriers in <u>existing facilities</u>, including communication barriers that are structural in nature, where design and construction for first occupancy started before January 26, 1993, and such removal is readily achievable, i.e., easily accomplishable and able to be carried out without much difficulty or expense⁶. Examples of steps to remove barriers include, but are not limited to, the following actions:

- 1) Installing ramps;
- 2) Making curb cuts in sidewalks and entrances;
- 3) Repositioning shelves;
- 4) Rearranging tables, chairs, vending machines, display racks, and other furniture;
- 5) Repositioning telephones;
- 6) Adding raised markings on elevator control buttons;
- 7) Installing flashing alarm lights;
- 8) Widening doors;
- 9) Installing offset hinges to widen doorways;
- 10) Eliminating a turnstile or providing an alternative accessible path;
- 11) Installing accessible door hardware;
- 12) Installing grab bars in toilet stalls;
- 13) Rearranging toilet partitions to increase maneuvering space;
- 14) Insulating lavatory pipes under sinks to prevent burns;
- 15) Installing a raised toilet seat;
- 16) Installing a full-length bathroom mirror;
- 17) Repositioning the paper towel dispenser in a bathroom;
- 18) Creating designated accessible parking spaces;

⁶ Department of Justice ADA Title III Regulations 28 CFR Part 36; Sec. 36.105 -- 36.199 [Reserved] Subpart B -- General Requirements Sec. 36.304 Removal of barriers.



- 19) Installing an accessible paper cup dispenser at an existing inaccessible water fountain;
- 20) Removing high pile, low density carpeting; or
- 21) Installing vehicle hand controls.

PRIORITIES

It is recommended that a public accommodation take measures to comply with the barrier removal requirements of this section in accordance with the following order of priorities:

- (1) A public accommodation should take measures to provide access to a place of public accommodation from public sidewalks, parking, or public transportation. These measures include, for example, installing an entrance ramp, widening entrances, and providing accessible parking spaces.
- (2) Second, a public accommodation should take measures to provide access to those areas of a place of public accommodation where goods and services are made available to the public. These measures include, for example, adjusting the layout of display racks, rearranging tables, providing Brailled and raised character signage, widening doors, providing visual alarms, and installing ramps.
- (3) Third, a public accommodation should take measures to provide access to restroom facilities. These measures include, for example, removal of obstructing furniture or vending machines, widening of doors, installation of ramps, providing accessible signage, widening of toilet stalls, and installation of grab bars.
- (4) Fourth, a public accommodation should take any other measures necessary to provide access to the goods, services, facilities, privileges, advantages, or accommodations of a place of public accommodation. This may include providing space in the seating area for wheelchair users to maneuver or wait, as able-bodied persons presently do.

No measure shall be taken; however, that poses a significant risk to the health or safety of individuals with disabilities or others. The provision of visual alarms is only required in sites where existing fire alarm systems are provided.

ALTERNATIVES TO BARRIER REMOVAL

Where a public accommodation cannot demonstrate that barrier removal is readily achievable, the public accommodation shall make its goods, services, facilities, privileges, advantages, or accommodations available through alternative methods, if those methods are readily achievable. Examples of alternatives to barrier removal include, but are not limited to, the following:

- (1) Providing curb service or home delivery;
- (2) Retrieving merchandise from inaccessible shelves or racks; and
- (3) Relocating activities to accessible locations.



Accessibility improvements for existing facilities must be viewed on a case-by-case basis; especially where space constraints or other extenuating circumstances may exist. Further, there may be instances where alterations that are otherwise necessary to provide fully compliant accessibility may be technically infeasible. In such cases, it is expected that alterations aimed at full compliance be made to the maximum extent feasible.

What does "maximum extent feasible" mean? In the context of ADA compliance, the "maximum extent feasible" refers to the greatest degree of alterations that can be made to existing sites and structures without adversely affecting:

- (1) the structural integrity of the site or structure;
- (2) the historical fabric of the site or structure; or
- (3) the naturally occurring geographic barriers surrounding the site or structure.

The fact that adding accessibility features during an alteration may increase costs does not, by itself, mean compliance is technically infeasible. Moreover, even if it is technically infeasible to comply with standards for individuals with certain disabilities (for instance, those who use wheelchairs), the alteration must still comply with standards for individuals with other impairments.⁷

ILLUSTRATION 1: A restaurant is undergoing a major renovation. Widening the entrance would affect the site structure because removal of an essential part of the structural frame would be required. In this case, it is "technically infeasible" to widen the entrance and the alteration is not required. However, all other CBC/ADA alterations requirements would apply to the renovation.

BUT: If the only problem with widening the entrance is that it would increase the cost of the renovation, the "technically infeasible" exception does not apply, and the entrance must be widened.

These issues have been taken into consideration while compiling this report. In cases where a facility was constructed since the enforcement of the ADA, full compliance is required.

B. SAFE HARBOR PROVISIONS

The County of Humboldt and private property owners can make use of the *safe harbor* provision contained in the 2010 ADA Standards. This federal rule applies to provisions in the ADA Standards and is applied on an element-by-element basis for elements that complied with the 1991 ADA Standards. The rule includes a general "safe harbor" under which physical elements in facilities used for County programs, activities and services, that were built or altered in compliance with the 1991 Standards, would not be required to be brought into compliance with the 2010 Standards until the elements were subject to a planned alteration. A similar safe harbor applies to elements associated with the "path of travel" to an altered area. The federal Access Board has provided a list of the new

Department of Justice: Americans with Disabilities Act ADA Title III Technical Assistance Manual Covering Public Accommodations and Commercial Facilities. III-6.1000 General.



requirements in the 2010 Standards that are not eligible for the safe harbor in § 35.150(b)(2)(ii)(A) through § 35.150(b)(2)(ii)(L) of the final rule⁸, which includes golf courses, recreation areas, play areas outdoor recreational areas and open spaces not originally covered by the 1990 Standards that are now included in the 2010 Standards.

The most common area where safe harbor applies in this particular facility is within the reach range requirements. Previous requirements under the 1990 ADA Standards allowed high reach range to extend to a maximum of 54 inches high, whereas the 2010 ADA Standards now allow a maximum reach of only 48 inches. Many controls and mechanisms can be granted safe harbor under this federal provision. Safe harbor does not apply to areas where an alteration to the permanent room or space has been performed since 1992, which required the element (e.g. light switch) to comply with the new construction standards in place at the time of the alteration.

C. BARRIER SEVERITY RATINGS AND REMEDIATION

SZS has developed proprietary barrier identification systems to standardize our process and ensure consistency while collecting data, creating reports and recommending implementation removal over time. Our proprietary barrier severity rating system was developed through many years of research and experience, and is integrated into our database, so that each barrier is assigned a rating that defines how severely each barrier affects a person's ability to use the element. We know from experience that without a systematic approach to barrier severity rating, deciding which barriers to remove, and when, can be reduced to guesswork.

There are five barrier severity ratings (BSR) that are assigned to individual barriers:

- 1 Necessary
- 2 Recommended
- 3 Hindrance
- 4 Low Severity
- 5 Technically Infeasible

The affect that the barrier has on a person using the element is important, but the date of construction also plays a role in determining barrier severity ratings. Facilities that are defined under the ADA as new construction are required to be fully compliant and the barrier severity rating assigned to those barriers is 1 — Necessary to Remove. That is a legal requirement that governs our work regardless of how minor a barrier may be in terms of how it affects the user.

In existing facilities, which were constructed prior to the passage of the ADA, barrier removal is not required to achieve new construction standards. The standard for barrier removal is to bring a facility into compliance to the maximum extent feasible. This standard takes into consideration past building standards and practices which did not comply to the current ADA standards. Where barrier severity ratings are 4- Low Severity, these barriers may not require remediation. When barriers are rated as a 5 – Technically Infeasible, they

Americans with Disabilities Act Title II Regulations, Part 35 Nondiscrimination on the Basis of Disability in State and Local Government Services (as amended by the final rule published on September 15, 2010) http://www.ada.gov/regs2010/titleII_2010/titleII_2010_regulations.htm





cannot be removed due to structural impracticability or other conditions that cannot be altered. Increasing the clear width of an interior stairway in an existing building, or reducing the roadway slope where it corresponds with steep terrain, is technically infeasible to remediate.

Sidewalks, which were constructed prior to 1992, were often constructed intentionally with a cross slope to encourage drainage that is now defined as a code violation. Research shows that the affect that the cross slope of a walking surface between 2.1% and 2.9% is minor, or of a low severity, and can be navigated by a person using a mobility assist device with some extra effort, whereas a cross slope of 5.0% or more is known to cause a wheelchair to tip over which may result in injury. Existing walkways and sidewalks that are identified with a cross slope in the 2.1% and 2.9% range are assigned a low severity BSR with remediation not generally recommended where the duration (linear footage) of the barrier is limited to less than 5 feet and the affect they have for people using mobility assist devices is minor in comparison to many other barriers identified. Other instances where barriers are identified in the report and no remediation is recommended will be provided with an explanation on a case-by-case basis.

Barriers with a low severity rating are often assigned a Proposed Solution of "No remediation recommended – low severity barrier". The California Division of State Architect has approved this approach for projects throughout the state, since it is reasonable and allows for funds to be concentrated on barrier removals that have hindered or prevented use of an element by people with disabilities.

D. OFFICIAL RESPONSIBLE

The County of Humboldt is responsible to ensure access for people with disabilities to the programs, services or activities that they provide, whether they are provided in owned or leased facilities. The County is not necessarily the responsible party entrusted with removing barriers in leased facilities. The county will work with property owners, where feasible, to ensure compliance. Under the federal statute, discrimination includes a failure to design and construct facilities for first occupancy after January 26, 1993, that are readily accessible to and usable by individuals with disabilities⁹. California government code, civil code, health and safety code, vehicle code and labor code contain similar requirements.

The designated ADA Coordinator (ADA CO) is in charge of the barrier remediation plan pursuant to the Project Civic Access Consent Decree and ADA Transition Plan remediation during the time in which these reports have been compiled. The ADA CO and/or representative can be reached at (844) 365-0352 or ADA@co.humboldt.ca.us. It is likely that the person in this position will change over time through attrition, or retirement. At that time, another ADA CO will be assigned and assume these responsibilities to ensure continuity of services.

E. RECOMMENDED BARRIER REMOVAL PRIORITIES

The functions within the buildings were assigned a barrier removal priority that corresponds with the regulations discussed above. All construction and alterations to County buildings and facilities by the County or on its behalf [in leased facilities] will comply with the

⁹ Subpart D – New Construction and Alterations. § 36.401 New construction. (a) General. (a)



requirements of 28 C.F.R. § 35.151, including applicable architectural standards. All architectural changes by the County or on its behalf made on or after March 15, 2012, must comply with the 2010 ADA Standards. The term "2010 ADA Standards" refers to the 2010 ADA Standards for Accessible Design (28 C.F.R. § 35.104 (Title II) (defining the "2010 ADA Standards" as the requirements set forth in appendices B and D to 36 C.F.R. part 1191 and the requirements contained in 28 C.F.R. § 35.151.)). All citations are to the 2010 ADA Standards unless otherwise noted.

The parts of a County facility that do not comply with the 1991 ADA Standards (or the 2010 ADA Standards, as applicable), as listed in Attachments G, H, I, and J, of the consent decree, prevent people with disabilities from fully and equally enjoying the County's programs, services, or activities and constitute discrimination on the basis of disability within the meaning of 42 U.S.C. § 12132 and 28 C.F.R. §§ 35.149-35.15110.

Facilities that are privately owned will remain under this consent decree whether or not the County continues to lease the facility to house programs, services and activities. As long as public accommodations continue to be provided in the facility, the requirement to remove barriers to access will remain in effect.

In addition, barrier removal priorities should reflect the way in which people use the facilities. For instance, if barrier removal is not completed and a person cannot reach the facility because there is no pedestrian access route from the public transportation provided to serve the building, or no accessible parking is provided, an accessible toilet room inside the building is of little use to people with disabilities.

In order to prioritize barrier removal within facilities for implementation we have correlated the County programs, activities and services that take place within buildings that serve people with disabilities with the barriers to access that have been identified. Barriers to access identified in the exterior and interior spaces have been prioritized according to the following criteria:

- **Priority 1:** Pedestrian route including access to the building from points of arrival and from the building site, including walkways and breezeways and potential hazards (see stairways below). Building entrances and lobby spaces
- **Priority 2**: Primary building functions (classrooms, meeting rooms, auditoriums, corridors, play areas, etc.)
- **Priority 3**: Restrooms, drinking fountains and benches or tables in public places
- **Priority 4**: Interior and exterior stairways, signage and remaining barriers that affect people with disabilities as a low severity barrier

Finalized barrier priorities can be influenced by information on other factors provided by the County of Humboldt. These factors include:

¹⁰ US v. County of Humboldt, Civil Action No. 16-5139, Section II.M: New Construction, Alterations, and Physical Changes to Facilities.



- Number and type of programs, services and activities that take place in the facility
- Frequency of use by the general public
- Age of facility (pre-1992 existing or new construction post-1992)
- Type of use (public, staff or mixed use)
- Long-term Facility Planning Goals
 - o Infrastructure improvement projects
 - o Facility replacement as part of future CIP plans

F. COST ESTIMATES

This report contains budgetary cost estimates provided to facilitate the remediation of barriers. Cost estimates are provided for physical elements only while the cost of implementing a new policy or practice cannot be accurately assessed at this point in the process. The actual cost estimates are calculated using RS Means Construction Cost Estimating data and in some instances where a barrier location can have several different barriers to access, one or more of the barriers may have a cost estimate of \$0 dollars. This is an intentional reporting mechanism as it reflects the fact that the cost to remove that particular barrier is part of a cost of one or more barriers at that same location.

For instance, where a door equipped with a door closer is identified with a non-compliant opening force, sweep period and a lack of required maneuvering clearance on one or both sides of that door, the recommended barrier removal solution is often to install an automatic door opening device (ADOD), which at the time of this assessment is estimated to cost \$5,000. If each of those barriers to access had been reported with a cost estimate, the estimate could amount to 3 times that much, or \$15,000 if the correction to 2 of the 3 cost estimates was not performed. The end result is intended to produce a budgetary cost estimate that does not include amounts that could exponentially increase the overall cost of barrier removal implementation plans.

G. EXTERIOR SPACES

This assessment process included identification of barriers to access within the pedestrian access route (accessible route within the public rights-of-way or PROW) that serves this facility. Under state and federal regulations and statutes, the pedestrian access route from points of arrival at public transportation stops (where provided), continuing through sidewalks (where provided) and walkways leading to the facility entrance must be accessible to people with disabilities in order to ensure that they can reach the facility where programs, services and activities are provided. This information is not contained in this report, but has been compiled into a separate report provided to each jurisdictional authority that owns the PROW that connects bus stops and sidewalks to this facility.

Where these jurisdictions make use of federal funding for roadway work, etc. the entity is required under the federal Rehabilitation Act of 1973 to ensure that the pedestrian access route is usable by and accessible to people with disabilities. The 1990 ADA Standards



provided additional requirements intended to ensure that these paths of travel are made fully accessible "as expeditiously as possible, but, in any event, by January 26, 1995".¹¹

At present, barriers were identified that appeared to be pre-ADA in some cases and these entities should be making progress on this work through a Rehabilitation Act Transition Plan since 1974 or ADA Transition Plan since 1992. If such plans are not in place, this information will be provided available to these entities, to allow them to make use of it when updating their existing remediation plans to comply with state and federal statutes and regulations.

This report contains barriers to access that are located within the facility site. There may be some overlap between site arrival points and a pedestrian connection to the facility entrance. In cases where the existing sidewalk is an essential part of the accessible route to the facility entrance, alterations must be made to the sidewalk to ensure that people with disabilities can make use of County programs, services and activities.

Owners of leased properties are likely to have responsibility for some of the sidewalk that borders their property.

As a public facility that was constructed before the passage of the ADA, the facility is required to have at least one accessible entrance and an accessible route provided within the building site that connects the existing sidewalk to the exterior and interior amenities provided, including a connection to public streets and sidewalks; and public transportation stops to the accessible building or facility entrance¹², as required by the 1990 and 2010 ADA Standards and California Code of Regulations Title 24.

H. FACILITY ENTRANCES

The entrance to the facility is located along the street frontage on the shortest possible route from the accessible parking provided.

¹¹ The Americans with Disabilities Act, Title II Technical Assistance Manual Covering State and Local Government Programs and Services, Section II-8.3000. See https://www.ada.gov/taman2.html#II-8.3000

¹² 2010 ADA Standards for Accessible Design, Section **206.2.1 Site Arrival Points**



I. REPORT FORMAT - DEFINITIONS

Field Date:	8/30/2016	Report Date:	9/13/2016	Barrier #: 1	A 1990 C
Facility:	Jail (Adult Dete	ention)			
Location:	Pedestrian Pat	h to Bullding			STATE OF THE PERSON NAMED IN
Official Resp	onsible:				
Facility Func	tion: Public			Dwg: 1 of 2	
Barrier Area:	Walkways		Remediat	ion: Required	
Sarrier Type	Detectable Wa	rnings - Hazardo	us Vehicular Way		
			TOTAL STATE OF THE		
Parrier	Detectable war		TE-MA	Il curb not provide	d at hazardous vehicular
Barrier Description:	Detectable war	rning (truncated	TE-MA	il curb not provide	d at hazardous vehicular
Barrier Description:	Detectable war	rning (truncated	domes) or vertica		d at hazardous vehicular
Barrier Description: Code Refere As Built	Detectable was nces: CBC 118-7 Pedestrian pati	rning (truncated 705.1.2.5 h along vehicular	domes) or vertica	no detectable was	//
Barrier Description: Code Refere As Built Description:	Detectable was nces: CBC 118-7 Pedestrian pati Provide trunca building entry	rning (truncated 705.1.2.5 h along vehicular ted domes as de	domes) or vertica r traffic lane has r tectable warning	no detectable was	ings installed where root
Barrier Description: Code Refere As Built Description: Proposed Solution:	Detectable was nces: CBC 118-7 Pedestrian pati Provide trunca building entry is: 194 Qu	rning (truncated 705.1.2.5 h along vehicular ted domes as de	domes) or vertica r traffic lane has r tectable warning	along pathway fro	ings installed where red in Chestout Avenue to

This is the Graphic User Interface (GUI) for the SZS database entry form. The name of each facility is located at the top of the form and the reports produced by the database have a similar format with identical fields although they are, in some instances, slightly different in size. A description for the data contained within each field is provided below:

- 1) Field Date: The date of the facility inspection.
- 2) Report Date: The date the report was compiled, revised or completed.
- 3) Barrier #: Individual number assigned to each barrier identified. The alphanumeric character assigned correlates with a room or space identified on the reference drawings provided with each report. This number allows the barrier to be pinpointed to a location within the facility.
- **4) Image:** Digital photograph provided for each barrier as a visual representation of the issue and context.
- 5) Facility: Name of building, park or parking lot where the inspection was performed
- 6) Location: Area or space within the facility where a barrier is identified
- 7) Official Responsible: Person responsible for overseeing the policies and practices implemented through this process





- 8) Facility Function (Public/Staff): Designates barriers as located in either staff or public areas. Most barriers identified are designated for public use. Different requirements exist for public and staff use areas.
- 9) Reference Drawing (Dwg): Floor, site plans or aerial maps of the designated facility where the assessment was performed. Each reference drawing provides correlation between the barrier number listed in the report (see item 3 above) and the actual physical location where the barrier was identified.
- **10) Barrier Area:** Provides a grouping of similar barriers identified in specific spaces (E.G.: Restrooms, Doors and Gates, Stairs, Ramps, Sidewalk, Walkways)
- 11) Remediation: Indicates whether a barrier is in direct violation of the federal and state codes and statutes and must be remediated or whether the remediation is recommended as a best practice. One of two options exist: (Required) or (Recommended).
- **12) Barrier Type:** Identifies the type of physical element or area defined by California Building Code and the ADA Standards used to identify non-compliance. The categories of barriers contained in the database include:

Alarms	
Assembly Areas	
Blended Transitions	
Bus Stops & Shelters	
Classrooms	
Clear Floor Space	
Controls and Mechanisms	
Corridors	
Counters and Tables	
Curb Ramps	
Dining Facilities	
Doors or Gates	
Drinking Fountains	
Elevators	
Kitchens	
Outdoor Areas Access Route	
Parking	
Passenger Loading Zones (Drop-Off)	
Picnic Facilities	
Play Areas	
Public Phones	
Ramps	
Restrooms	
Signage	
Stairways	
Street Furniture	
Swimming Pools	



Turning Space	
Walkways	

- **13) Requirement (Barrier Description):** Code language or performance standard that describes barrier identified.
- 14) Code References: Applicable state and federal codes regulating the entities compliance. Each code reference is specific to each barrier and identifies the section of code which regulates compliance to that specific element (doors, parking stalls, sidewalks, etc.). Where a best practice is recommended, the term *Performance Standard* identifies the barrier to access documented in the barrier data record.
- 15) As Built Description (Desc): Also known as the findings, information describes the barrier.
- **16) Proposed Solution:** Provides one suggested solution for the remediation of the barrier identified. Please note that other options may exist to bring items into compliance. Other solutions may exist and all solutions cannot be accounted for in this report. The suggested solution is generally the most common way of remediating this particular barrier.
- 17) As Built Measure: Actual field measurement number for square footage (SF), linear footage (LF), or a single value (EACH or JOB) used to indicate physical dimension of barrier and calculate cost estimate.
- 18) Quantity: Unit of measure for the remediation of each barrier (SF, LF, EACH or JOB).
- 19) Cost Estimate: Budgetary Cost Estimate to remove the barrier described.
- **20) Barrier Severity Rating (BSR):** A systematic, research based rating that describes how severely each barrier affects usability for the particular element.
- 21) X Coordinate: Geographic coordinate that provides the longitude (north-south) value
- 22) Y Coordinate: Geographic coordinate that provides the latitude (east-west) value
- 23) Z Coordinate: Geographic coordinate that provides the elevation value
- 24) Implementation Priority: N/A
- 25) Implementation Phase: N/A
- **26) Implementation Date:** Scheduled year or date as to when the remediation of the barrier will take place within the consent decree schedule. This field can be scheduled during phasing and changed to a specific date after the barrier is remediated and the record is closed.
- 27) Status (Open or Closed): An implementation management tool that can flag barriers to indicate that they have been remediated or are remaining in the implementation phasing plan. Barrier data records have a "Closed" status when completed or have an "Open" status when they remain scheduled for remediation. This can be useful when remediation is



performed by both maintenance staff and design professionals within the construction process.

28) Notes: Open field where additional explanation of the findings can be noted when encountering unusual situations in the field, or to note programmatic access solutions. The notes field can contain the image file name shown in the barrier data record, or additional information as needed such as an explanation of findings, or information on associated barriers in the same or similar locations.

EXTERIOR SPACES

The path of travel from the nearest bus stop was assessed as part of the scope of work. People with disabilities often travel using regional transit and must have an accessible route that allows them to reach the facility. Bus stops serving the facility are not identified with signs and the busses stop in the roadway. Barriers to access were identified which may be the responsibility of another local jurisdiction to remediate. The jurisdiction should be contacted in order to ensure that these barriers are removed so that the County program, services and activities that take place in this location are accessible to people with disabilities.

Redway is a small, rural town with few locations where sidewalk is provided. While sidewalk is provided in front of the facility, most of the remaining pedestrian access route is located in the roadway shoulder.

INTERIOR SPACES

The facility consists of a large, open space with a toilet room vestibule and single user toilet room. The entrance door landing was identified with a non-compliant slope, which could be remediated by installing an automatic door opening device. The open work space was not identified with barriers to access, other than the light switches and electrical outlets that were not identified within an accessible reach range. No drinking fountains were identified at any location in this facility, which is in violation of California Plumbing Code. Door closers were not installed on doors to the toilet room vestibule or the toilet room.

Signs indicating the location of the toilet room were not provided on the vestibule door or toilet room door. The toilet room vestibule door was located adjacent to a structural support, where maneuvering clearance at the door was not compliant. The door would need to be altered to be accessible on the exit side of the door. The toilet room was identified with several barriers to access which could be remediated with little effort or expense.

The following barrier data records provide more detailed information on the barriers described above.



Field Date:	2/28/2019 Repor	t Date: 3/8/2019 B	Sarrier #: 1A	
Facility:	3156 Redwood Drive, F	Redway		
Location:	Exterior - On-Street Par	rking	//	
Official Respo	nsible: Karen Clower,	Interim ADA Coordinator		
Consent Decr	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Parking	Remediatio	n: Required	
Barrier Type:	Tow-Away Sign			
Barrier Description:	No tow-away sign prov	ided at lot entry or accessi	ble stalls	
Code Referen	ces: CBC 11B-502.8			
As Built Description:	No sign provided			
Proposed Solution:	Provide compliant sign			
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$	250.00 BSR: 2	Recommended
X Coordinate:	-123.819958	Y Coordinate: 40.11749	Z Coordinat	e: 148.3
Implementati	on: Priority 1	Phase	Date	Status Open
Notes:				
Field Date:	2/28/2019 Repor	t Date: 3/8/2019 B	arrier #: 1B	L 🏮
Facility:	3156 Redwood Drive, R	tedway		o de la companya de l
Location:	Exterior - On-Street Par	king		
Official Respo	nsible: Karen Clower,	Interim ADA Coordinator		
Consent Decre		Paragraph: M.51	Dwg: N/A	
Barrier Area:	Parking	Remediatio	n: Required	4 A
Barrier Type:	Accessible Stall Sign - H	eight		1
Barrier Description:	Reflectorized ISA sign is	not posted with bottom e	dge at min. 60" high	
Code Referen	ces: CBC 11B-502.6 and	1 2010 ADAS 502.6		
As Built Description:	46" high van accessible	sign below ISA sign that w	as posted at 60" high	
Proposed Solution:	Remount sign with bott	om edge at a minimum of	60" high	
As-Built Meas	Quantity:	EACH Cost Estimate: \$	100.00 BSR: 2	Recommended
X Coordinate:	-123.819958	Y Coordinate: 40.11749	Z Coordinate	e: 148.3
Implementation	on: Priority 1	Phase	Date	Status Open
Notes:				



Field Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 1C	State of the state
Facility: 3156 Redwood Drive, Redway	
Location: Exterior - On-Street Parking	86
Official Responsible: Karen Clower, Interim ADA Coordinator	Alle
Consent Decree: No Paragraph: M.51 Dwg: N/A	
Barrier Area: Parking Remediation: Required	
Barrier Type: Accessible Stall Aisle - NO PARKING Lettering	
Barrier Access aisle lacks sign stating "NO PARKING" with min. 12" high letters contrasting surface	g with stall
Code References: CBC 11B-502.3.3	·
As Built Marking not within aisle Description:	
Proposed Provide required pavement sign at bottom of access aisle Solution:	
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$150.00 BSR: 3 Hindrane	ce
X Coordinate: -123.819958 Y Coordinate: 40.11749 Z Coordinate: 148.3	3
Implementation: Priority 1 Phase Date Status	Open
Notes:	
Field Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 1D	7
Field Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 1D Facility: 3156 Redwood Drive, Redway	THE REAL PROPERTY.
Facility: 3156 Redwood Drive, Redway	
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking	
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator	
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A	
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Parking Remediation: Required	idth of
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Parking Remediation: Required Barrier Type: Accessible Stall - Clear Width of Connecting Accessible Route Wheelstop or curb not provided to prevent parked vehicle from reducing clear wid	dth of
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Parking Remediation: Required Barrier Type: Accessible Stall - Clear Width of Connecting Accessible Route Wheelstop or curb not provided to prevent parked vehicle from reducing clear wide Description: accessible route to less than 48" wide	
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Parking Remediation: Required Barrier Type: Accessible Stall - Clear Width of Connecting Accessible Route Barrier Description: Wheelstop or curb not provided to prevent parked vehicle from reducing clear wide Code References: CBC 11B-206.2.2 and 2010 ADAS 206.2.2 As Built No wheelstop provided where vertical curb is not provided due to tapered curb at	t access aisle
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Parking Remediation: Required Barrier Type: Accessible Stall - Clear Width of Connecting Accessible Route Barrier Wheelstop or curb not provided to prevent parked vehicle from reducing clear wide Description: accessible route to less than 48" wide Code References: CBC 11B-206.2.2 and 2010 ADAS 206.2.2 As Built Description: Proposed Provide wheelstop secured with steel reinforcing bars. Recommended: place wheelstop in the provided of the place wheelstop secured with steel reinforcing bars. Recommended: place wheelstop in the place wheelstop secured with steel reinforcing bars. Recommended: place wheelstop in the place wheelstop secured with steel reinforcing bars. Recommended: place wheelstop secured with steel reinforcing bars.	t access aisle elstop 2 feet
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Parking Remediation: Required Barrier Type: Accessible Stall - Clear Width of Connecting Accessible Route Barrier Wheelstop or curb not provided to prevent parked vehicle from reducing clear wide accessible route to less than 48" wide Code References: CBC 11B-206.2.2 and 2010 ADAS 206.2.2 As Built Description: Proposed Provide wheelstop secured with steel reinforcing bars. Recommended: place wheelstop in the provided of stall As-Built Meas: 1 Quantity: JOB Cost Estimate: \$250.00 BSR: 3 Hindrand X Coordinate: -123.819958 Y Coordinate: 40.11749 Z Coordinate: 148.3	t access aisle elstop 2 feet ce
Facility: 3156 Redwood Drive, Redway Location: Exterior - On-Street Parking Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Parking Remediation: Required Barrier Type: Accessible Stall - Clear Width of Connecting Accessible Route Barrier Wheelstop or curb not provided to prevent parked vehicle from reducing clear wide accessible route to less than 48" wide Code References: CBC 11B-206.2.2 and 2010 ADAS 206.2.2 As Built Description: Proposed Provide wheelstop secured with steel reinforcing bars. Recommended: place wheelstop in the provided of stall As-Built Meas: 1 Quantity: JOB Cost Estimate: \$250.00 BSR: 3 Hindrand X Coordinate: -123.819958 Y Coordinate: 40.11749 Z Coordinate: 148.3	t access aisle elstop 2 feet ce



Field Date:					
	2/28/2019	Report Date: 3/8/2019	Barrier #:	1E	Ann Land I was
Facility:	3156 Redwood D	rive, Redway			
Location:	Exterior - On-Stre	et Parking			
Official Respo	nsible: Karen Cl	ower, Interim ADA Coor	dinator		
Consent Decr	ee: No	Paragraph: M.51	Dwg	N/A	MAA
Barrier Area:	Parking	Rei	mediation: Requ	uired	
Barrier Type:	Accessible Stall A	isle - Cross-hatching			
Barrier Description:	Access aisle not o	ross-hatched with hatch	ed lines striped a	at 36" on cen	ter
Code Referen	ces: CBC 11B-502	2.3.3 and 2010 ADAS 502	.3.3		
As Built Description:	43" OC				*
Proposed Solution:	Restripe access a	isle			
As-Built Meas	: 1 Quar	ntity: EACH Cost Estin	nate: \$450.00	BSR:	3 Hindrance
X Coordinate:	-123.819958	Y Coordinate: 40.	11749	Z Coordin	ate: 148.3
Implementati	on: Priority 1	Phase	Date		Status Open
Notes:					
Field Date:	2/28/2019	Report Date: 3/8/2019	Barrier #:	1F	
	1-,-0,-0-5	1 10/0/2020		.0.	
Facility:	3156 Redwood D				A
Facility: Location:		rive, Redway			
Location:	3156 Redwood D Exterior - On-Stre	rive, Redway			
Location:	3156 Redwood D Exterior - On-Stre nsible: Karen Cl	rive, Redway et Parking	linator	: N/A	
Location: Official Respo	3156 Redwood D Exterior - On-Stre nsible: Karen Cl ee: No	rive, Redway et Parking ower, Interim ADA Coord Paragraph: M.51	linator	: N/A	
Location: Official Respo Consent Decre Barrier Area:	3156 Redwood D Exterior - On-Stre nsible: Karen Cl ee: No	rive, Redway et Parking ower, Interim ADA Coord Paragraph: M.51 Rei	dinator Dwg:	: N/A	
Location: Official Respo Consent Decre Barrier Area:	3156 Redwood D Exterior - On-Stre nsible: Karen Cl ee: No Parking Stall Slope - Existi	rive, Redway et Parking ower, Interim ADA Coord Paragraph: M.51 Rei	Dwg:	: N/A	
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	3156 Redwood D Exterior - On-Streensible: Karen Clee: No Parking Stall Slope - Existing Accessible stall &	rive, Redway eet Parking ower, Interim ADA Coord Paragraph: M.51 Rei ng (4.1% to 4.9%)	Dwg nediation: N/A	: N/A	
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	3156 Redwood D Exterior - On-Streensible: Karen Clee: No Parking Stall Slope - Existing Accessible stall & Ces: CBC 11B-502	rive, Redway eet Parking ower, Interim ADA Coord Paragraph: M.51 Rei fing (4.1% to 4.9%) aisle not max. 2.0% in a	Dwg. mediation: N/A	N/A % to 4.9%)	vere slope
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referen As Built	3156 Redwood D Exterior - On-Streensible: Karen Clee: No Parking Stall Slope - Existing Accessible stall & Ces: CBC 11B-502 4.3% slope at 16'	rive, Redway eet Parking ower, Interim ADA Coord Paragraph: M.51 Rei ng (4.1% to 4.9%) aisle not max. 2.0% in a	Dwg. mediation: N/A Il directions (4.19	N/A to 4.9%)	
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed	3156 Redwood D Exterior - On-Streensible: Karen Clee: No Parking Stall Slope - Existing Accessible stall & Ces: CBC 11B-502 4.3% slope at 16' No remediation roadway slope	rive, Redway eet Parking ower, Interim ADA Coord Paragraph: M.51 Ren ing (4.1% to 4.9%) aisle not max. 2.0% in a	dinator Dwg. mediation: N/A Il directions (4.19 nto roadway should a company should be company sho	N/A to 4.9%) ulder with se	
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution: As-Built Meas	3156 Redwood D Exterior - On-Streensible: Karen Clee: No Parking Stall Slope - Existing Accessible stall & Ces: CBC 11B-502 4.3% slope at 16' No remediation roadway slope	rive, Redway eet Parking ower, Interim ADA Coord Paragraph: M.51 Rei ing (4.1% to 4.9%) aisle not max. 2.0% in a 4.4 and 2010 ADAS 502.4 where stall transitions in	dinator Dwg mediation: N/A Il directions (4.19 nto roadway sho	N/A to 4.9%) ulder with seto comply du	e to transition from
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution: As-Built Meas	3156 Redwood D Exterior - On-Streensible: Karen Clee: No Parking Stall Slope - Existing Accessible stall & Ces: CBC 11B-502 4.3% slope at 16' No remediation remadway slope : O Quaring -123.819958	rive, Redway eet Parking ower, Interim ADA Coord Paragraph: M.51 Ren ing (4.1% to 4.9%) aisle not max. 2.0% in a 2.4 and 2010 ADAS 502.4 where stall transitions in equired where it is techn atity: EACH Cost Estim	dinator Dwg mediation: N/A Il directions (4.19 nto roadway sho	N/A to 4.9%) ulder with seto comply du	e to transition from 5 Technically Infeasible



Field Catal				
Field Date:	2/28/2019 Repo	ort Date: 3/8/2019	Barrier #:	2A
Facility:	3156 Redwood Drive,	Redway		
Location:	Entrance Door			TO THE
Official Respo	nsible: Karen Clower	, Interim ADA Coordinat	or	
Consent Decr	ee: No	Paragraph: M.51	Dwg:	N/A
Barrier Area:	Signage	Remedi	ation: Requir	ed
Barrier Type:	ISA - Accessible Entry			
Barrier Description:	No sign identifying do	or as accessible		
Code Referen	ces: CBC 11B-216.6 ar	nd 2010 ADAS 216.6		
As Built Description:	Accessible entrance ha	as no ISA sign		
Proposed Solution:	Provide ISA at accessib	ole entrance door		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$250.00	BSR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A		Z Coordinate: N/A
Implementati	on: Priority 4	Phase	Date	Status Open
Notes:				
Field Date:	2/28/2019 Repo	rt Date: 3/8/2019	Barrier #:	2B
Field Date: Facility:	2/28/2019 Repo 3156 Redwood Drive,		Barrier #:	2B
Facility:	<u> </u>		Barrier #:	2B
Facility:	3156 Redwood Drive, Entrance Door			2B
Facility: Location:	3156 Redwood Drive, Entrance Door nsible: Karen Clower	Redway		
Facility: Location: Official Respo	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No	Redway , Interim ADA Coordinato Paragraph: M.51	or	N/A
Facility: Location: Official Respo Consent Decre Barrier Area:	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No	Redway , Interim ADA Coordinato Paragraph: M.51 Remedia	or Dwg: ∫i	N/A
Facility: Location: Official Respo Consent Decre Barrier Area:	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No Signage Room ID Sign - No Sign	Redway , Interim ADA Coordinato Paragraph: M.51 Remedia	or Dwg: ∫i ation: Requir	N/A
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No Signage Room ID Sign - No Sign	Redway , Interim ADA Coordinate Paragraph: M.51 Remedia ded at permanent room	or Dwg: ∫i ation: Requir	N/A
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No Signage Room ID Sign - No Sign	Redway , Interim ADA Coordinate Paragraph: M.51 Remedia n ded at permanent room ad 2010 ADAS 216.2	or Dwg: ∫i ation: Requir	N/A
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No Signage Room ID Sign - No Sign No room ID sign provides: CBC 11B-216.2 an	Redway , Interim ADA Coordinate Paragraph: M.51 Remedia n ded at permanent room ad 2010 ADAS 216.2	or Dwg: ∫i ation: Requir or space	N/A ed
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No Signage Room ID Sign - No Sign No room ID sign providees: CBC 11B-216.2 an No identification sign provide room ID sign v	Redway , Interim ADA Coordinate Paragraph: M.51 Remedia ded at permanent room ad 2010 ADAS 216.2 provided	Dwg: Ji ntion: Requir or space	N/A ed
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No Signage Room ID Sign - No Sign No room ID sign provide ces: CBC 11B-216.2 an No identification sign provide room ID sign v	Redway , Interim ADA Coordinate Paragraph: M.51 Remedia ded at permanent room ad 2010 ADAS 216.2 provided with tactile information a	Dwg: Ji ntion: Requir or space	N/A ed side of door
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas:	3156 Redwood Drive, Entrance Door nsible: Karen Clower ee: No Signage Room ID Sign - No Sign No room ID sign provide ces: CBC 11B-216.2 an No identification sign provide room ID sign v Provide room ID sign v 1 Quantity:	Redway , Interim ADA Coordinate Paragraph: M.51 Remedia ded at permanent room ad 2010 ADAS 216.2 provided with tactile information a	Dwg: Ji ntion: Requir or space	N/A ed side of door BSR: 1 Necessary



eld Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 2C
acility: 3156 Redwood Drive, Redway
ocation: Entrance Door
fficial Responsible: Karen Clower, Interim ADA Coordinator
onsent Decree: No Paragraph: M.51 Dwg: N/A
arrier Area: Doors or Gates Remediation: Required
arrier Type: Door/Gate Landing - Slope 2.1% to 3.0%
Door/Gate landing is not level on both sides of door (2.1% to 3.0%) escription:
ode References: CBC 11B-404.2.4.4 and 2010 ADAS 404.2.4.4
2.8% door landing slope escription:
Demolish and reconstruct level landing or install automatic door opening device plution:
s-Built Meas: 40 Quantity: SF Cost Estimate: \$5,000.00 BSR: 4 Low Severity
Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
plementation: Priority 2 Phase Date Status Open
otes:
eld Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 2D
cility: 3156 Redwood Drive, Redway
0
acility: 3156 Redwood Drive, Redway
accility: 3156 Redwood Drive, Redway Cocation: Entrance Door Corporation: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A
acility: 3156 Redwood Drive, Redway Scation: Entrance Door Fficial Responsible: Karen Clower, Interim ADA Coordinator
accility: 3156 Redwood Drive, Redway Cocation: Entrance Door Corporation: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A
accility: 3156 Redwood Drive, Redway Cocation: Entrance Door Corporation: Entrance Door Consent Decree: No Paragraph: M.51 Dwg: N/A Corrier Area: Doors or Gates Remediation: Required
accility: 3156 Redwood Drive, Redway Entrance Door Fficial Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Courrier Area: Doors or Gates Remediation: Required Courrier Type: Threshold (replacement) Coor/Gate threshold height exceeds 1/2" with a bevel
acation: Entrance Door Fficial Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Courrier Area: Doors or Gates Remediation: Required Courrier Type: Threshold (replacement) Door/Gate threshold height exceeds 1/2" with a bevel
accility: 3156 Redwood Drive, Redway Entrance Door Ficial Responsible: Karen Clower, Interim ADA Coordinator Ensent Decree: No Paragraph: M.51 Dwg: N/A Enrier Area: Doors or Gates Remediation: Required Enrier Type: Threshold (replacement) Door/Gate threshold height exceeds 1/2" with a bevel Escription: CBC 11B-404.2.5 and 2010 ADAS 404.2.5 Built 1" high threshold
acation: Entrance Door Ficial Responsible: Karen Clower, Interim ADA Coordinator Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Area: Doors or Gates Remediation: Required Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Insent Decree: Door Gate threshold height exceeds 1/2" with a bevel Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Insent Decree: Door Gates Remediation: Required Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshol
acation: Entrance Door Ficial Responsible: Karen Clower, Interim ADA Coordinator Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Area: Doors or Gates Remediation: Required Inrier Type: Threshold (replacement) Inrier Pescription: Door/Gate threshold height exceeds 1/2" with a bevel In the decrease CBC 11B-404.2.5 and 2010 ADAS 404.2.5 In the built Provide new door threshold or alter landing to comply lution: In the decrease of the should or alter landing to comply lution:
acation: Entrance Door Ficial Responsible: Karen Clower, Interim ADA Coordinator Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Area: Doors or Gates Remediation: Required Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Insent Decree: Door Gate threshold height exceeds 1/2" with a bevel Insent Decree: No Paragraph: M.51 Dwg: N/A Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Insent Decree: Door Gates Remediation: Required Inrier Type: Threshold (replacement) Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshold height exceeds 1/2" with a bevel Inrier Door/Gate threshol

Field Date: 2/28/2019	Report Date:	3/8/2019	Barrier #:	2E
Facility: 3156 Redwo	ood Drive, Redway	,	111	
Location: Entrance Do	oor			
Official Responsible: Kar	en Clower, Interin	n ADA Coordinato	or	
Consent Decree: No		aph: M.51	Dwg: N	/A
Barrier Area: Doors or Ga	ites	Remedia	tion: Require	ed
Barrier Type: Door Closer	- Exterior Adjustm	nent		
Barrier Door openin	ng force exceeds 5	lbf		
Code References: CBC 11	B-404.2.9			
As Built 14 lbf Description:				
Proposed Replace or a Solution:	adjust existing clos	er or install autor	matic door ope	ening device
As-Built Meas: 1	Quantity: EACH	Cost Estimate:	\$450.00	BSR: 1 Necessary
X Coordinate: N/A	Y Coord	dinate: N/A		Z Coordinate: N/A
Implementation: Priority	2 Phase		Date	Status Open
Notes:				
r			and the same of th	(
Field Date: 2/28/2019	Report Date:	3/8/2019	Barrier #: 2	2F
	Report Date: ood Drive, Redway		Barrier #: 2	CF CF
	ood Drive, Redway		Barrier #: 2	2F
Facility: 3156 Redwo	ood Drive, Redway			2F
Facility: 3156 Redwo	ood Drive, Redway oor en Clower, Interim			
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar	ood Drive, Redway oor en Clower, Interin Paragra	n ADA Coordinato	or	/A
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar Consent Decree: No	ood Drive, Redway oor en Clower, Interin Paragra	n ADA Coordinato	or Dwg: N	/A
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar Consent Decree: No Barrier Area: Doors or Ga Barrier Type: Door Closer	ood Drive, Redway oor en Clower, Interin Paragra	n ADA Coordinato aph: M.51 Remedia	Dwg: N	/A
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar Consent Decree: No Barrier Area: Doors or Ga Barrier Type: Door Closer Barrier Door closer	ood Drive, Redway oor en Clower, Interim Paragra tes - Exterior Sweep lacks min. 5 secon	n ADA Coordinato aph: M.51 Remedia d sweep period/l	Dwg: N tion: Require	/A
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar Consent Decree: No Barrier Area: Doors or Ga Barrier Type: Door Closer Description:	ood Drive, Redway oor en Clower, Interim Paragra tes - Exterior Sweep lacks min. 5 secon	n ADA Coordinato aph: M.51 Remedia d sweep period/l	Dwg: N tion: Require	/A
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar Consent Decree: No Barrier Area: Doors or Ga Barrier Type: Door Closer Barrier Description: Code References: CBC 11 As Built Description: 3 second sw	ood Drive, Redway oor en Clower, Interim Paragra tes - Exterior Sweep lacks min. 5 secon	n ADA Coordinato aph: M.51 Remedia d sweep period/l	Dwg: N tion: Require back check	/A ad
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar Consent Decree: No Barrier Area: Doors or Ga Barrier Type: Door Closer Barrier Description: Code References: CBC 11 As Built Description: Replace or a Solution:	ood Drive, Redway oor en Clower, Interim Paragra tes - Exterior Sweep lacks min. 5 secon B-404.2.8.1 and 20	n ADA Coordinato aph: M.51 Remedia d sweep period/l 010 ADAS 404.2.8	Dwg: N tion: Require back check	/A ad
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar Consent Decree: No Barrier Area: Doors or Ga Barrier Type: Door Closer Barrier Description: Code References: CBC 11 As Built Description: Replace or a Solution:	tes - Exterior Sweep lacks min. 5 secon B-404.2.8.1 and 20 reep djust existing clos	n ADA Coordinato aph: M.51 Remedia d sweep period/l 010 ADAS 404.2.8	Dwg: Note that the property of	And Park Park Park Park Park Park Park Park
Facility: 3156 Redword Location: Entrance Do Official Responsible: Kar Consent Decree: No Barrier Area: Doors or Ga Barrier Type: Door Closer Barrier Description: Code References: CBC 11 As Built Description: Replace or a Solution: As-Built Meas: 0	pood Drive, Redway for en Clower, Interim Paragra tes - Exterior Sweep lacks min. 5 secon B-404.2.8.1 and 20 reep adjust existing clos Quantity: EACH Y Coord	n ADA Coordinato aph: M.51 Remedia d sweep period/l 010 ADAS 404.2.8 er or install autor Cost Estimate:	Dwg: Note that the property of	ening device BSR: 2 Recommended

Field Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 2G
Facility: 3156 Redwood Drive, Redway
Location: Entrance Door
Official Responsible: Karen Clower, Interim ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: N/A
Barrier Area: Signage Remediation: Required
Barrier Type: Tactile Exit Sign - Exit
Ground floor doors that exit to exterior not provided with signs stating "EXIT" Description:
Code References: CBC 11B-216.4.1 & 11B-703 and 2010 ADAS 216.4.1
As Built No tactile sign provided where required Description:
Proposed Provide compliant sign at exit side of door Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary
Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
mplementation: Priority 4 Phase Date Status Open
Notes:
Field Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 3A
Facility: 3156 Redwood Drive, Redway
Facility: 3156 Redwood Drive, Redway
Facility: 3156 Redwood Drive, Redway Location: Interior Space
Cacility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Controls and Mechanisms Remediation: Required
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Electrical Outlets - Side Reach Low Unobstructed Electrical outlet control box not min. 15" high measured to the bottom of the outlet box
Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Electrical Outlets - Side Reach Low Unobstructed Electrical outlet control box not min. 15" high measured to the bottom of the outlet box Description:
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Electrical Outlets - Side Reach Low Unobstructed Barrier Description: Electrical outlet control box not min. 15" high measured to the bottom of the outlet box Code References: CBC 11B-308.1.2, 11B-308.3.1 and 2010 ADAS 308.3 As Built 11-1/2" high
Sacrier Type: Electrical Outlets - Side Reach Low Unobstructed Barrier Type: Electrical outlet control box not min. 15" high measured to the bottom of the outlet box Code References: CBC 11B-308.1.2, 11B-308.3.1 and 2010 ADAS 308.3 As Built Description: Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Redwood Drive, Redway M.51 Dwg: N/A Remediation: Required Barrier Type: Electrical Outlets - Side Reach Low Unobstructed Barrier Description: CBC 11B-308.1.2, 11B-308.3.1 and 2010 ADAS 308.3 Responsible: Karen Clower, Interim ADA Coordinator Dwg: N/A Remediation: Required Barrier Type: Electrical Outlets - Side Reach Low Unobstructed Barrier Description: Required Barrier Type: Electrical Outlets - Side Reach Low Unobstructed Barrier Type: Electrical Outlets - Side Reach Low Unob
Sacrier Type: Electrical Outlets - Side Reach Low Unobstructed Barrier Type: Electrical outlet control box not min. 15" high measured to the bottom of the outlet box Code References: CBC 11B-308.1.2, 11B-308.3.1 and 2010 ADAS 308.3 As Built Description: Relocate switch box to min. 15" high at the bottom of the outlet box Relocate switch box to min. 15" high at the bottom of the outlet box Relocate switch box to min. 15" high at the bottom of the outlet box
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Electrical Outlets - Side Reach Low Unobstructed Barrier Description: Electrical outlet control box not min. 15" high measured to the bottom of the outlet box Code References: CBC 11B-308.1.2, 11B-308.3.1 and 2010 ADAS 308.3 As Built Description: Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box Code References: Interior Proposed Relocate switch box to min. 15" high at the bottom of the outlet box

Field Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 3B
Facility: 3156 Redwood Drive, Redway
Location: Interior Space
Official Responsible: Karen Clower, Interim ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: N/A
Barrier Area: Controls and Mechanisms Remediation: Required
Barrier Type: Electrical Switches - Side Reach High Unobstructed
Barrier Light switch control box not max. 48" high measured to the top of the outlet box Description:
Code References: CBC 11B-308.1.1, 11B-308.3.1 and 2010 ADAS 308.3
As Built 48-1/3" high Description:
Proposed Relocate switch box to max. 48" high measured to the top of the outlet box Solution:
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$750.00 BSR: 3 Hindrance
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes:
Field Date: 2/28/2019 Report Date: 3/8/2019 Barrier #: 3C
12/26/2015 Report Bate. 15/6/2015 Battlet W. 150
Facility: 3156 Redwood Drive, Redway
Facility: 3156 Redwood Drive, Redway
Facility: 3156 Redwood Drive, Redway Location: Interior Space
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Drinking Fountains Remediation: Required
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Drinking Fountains Remediation: Required Barrier Type: Drinking Fountain - No Fixture Provided Barrier No drinking fountain is provided in facility
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Drinking Fountains Remediation: Required Barrier Type: Drinking Fountain - No Fixture Provided No drinking fountain is provided in facility Description:
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Drinking Fountains Remediation: Required Barrier Type: Drinking Fountain - No Fixture Provided Barrier Description: Code References: CBC 11B-211.2 and 2010 ADAS 211.2 As Built No drinking fountain of any type provided. Hi-low fountain required.
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Drinking Fountains Remediation: Required Barrier Type: Drinking Fountain - No Fixture Provided Barrier Poscription: Code References: CBC 11B-211.2 and 2010 ADAS 211.2 As Built Description: Proposed Provide min. two drinking fountains to serve standing people and people using wheelchairs
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Drinking Fountains Remediation: Required Barrier Type: Drinking Fountain - No Fixture Provided Barrier Description: Code References: CBC 11B-211.2 and 2010 ADAS 211.2 As Built Description: Proposed Solution: Provide min. two drinking fountains to serve standing people and people using wheelchairs
Facility: 3156 Redwood Drive, Redway Location: Interior Space Official Responsible: Karen Clower, Interim ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Drinking Fountains Remediation: Required Barrier Type: Drinking Fountain - No Fixture Provided Barrier Description: Code References: CBC 11B-211.2 and 2010 ADAS 211.2 As Built Description: Proposed Provide min. two drinking fountains to serve standing people and people using wheelchairs Solution: As-Built Meas: 1 Quantity: JOB Cost Estimate: \$1,440.00 BSR: 1 Necessary

	2/28/2019 Repo	rt Date: 3/8/2019	Barrier #: 4A		
Facility:	3156 Redwood Drive, Redway				
Location:	Toilet Room Vestibule				
Official Respo	nsible: Karen Clower	, Interim ADA Coordinat	tor		
Consent Decr	ee: No	Paragraph: M.51	Dwg: N/A	1	
Barrier Area:	Signage	Remedi	iation: Required		
Barrier Type:	Room ID Sign - No Sign	1			
Barrier Description:	No room ID sign provid	ded at permanent room	or space	*	
Code Referen	ces: CBC 11B-216.2 an	d 2010 ADAS 216.2			
As Built Description:	No identification sign a	at vestibule leading to to	oilet room		
Proposed Solution:	Provide room ID sign v	vith tactile information	at wall at latch sid	e of door	
As-Built Meas	Quantity:	EACH Cost Estimate:	\$250.00	BSR: 1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z (Coordinate: N/A	
Implementati	on: Priority 4	Phase	Date	Status Open	
Notes:					
Field Date:	2/28/2019 Repor	rt Date: 3/8/2019	Barrier #: 4B		
Facility:	3156 Redwood Drive,	Redway			
,	jorso neavoca brive,	ncuvay			
Location:	Toilet Room Vestibule	Neuway			
Location:			or	in the second	
Location:	Toilet Room Vestibule		or Dwg: N/A		
Location: Official Respo	Toilet Room Vestibule nsible: Karen Clower, ee: No	Interim ADA Coordinat			
Location: Official Respo Consent Decre Barrier Area:	Toilet Room Vestibule nsible: Karen Clower, ee: No	Interim ADA Coordinat Paragraph: M.51 Remedi	Dwg: N/A		
Location: Official Respo Consent Decre Barrier Area:	Toilet Room Vestibule nsible: Karen Clower, ee: No Restrooms Sign - 12" Circle/Triang	Interim ADA Coordinat Paragraph: M.51 Remedi tle at Unisex Restroom	Dwg: N/A Required	doorway to unisex toilet room	
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Toilet Room Vestibule nsible: Karen Clower, ee: No Restrooms Sign - 12" Circle/Triang	Interim ADA Coordinat Paragraph: M.51 Remedi tle at Unisex Restroom mposed on 12" circle pr	Dwg: N/A Required		
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Toilet Room Vestibule nsible: Karen Clower, ee: No Restrooms Sign - 12" Circle/Triang No 12" triangle superir ces: CBC 11B-703.7.2.6	Interim ADA Coordinat Paragraph: M.51 Remedi tle at Unisex Restroom mposed on 12" circle pr	Dwg: N/A fation: Required ovided on door or		
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code References	Toilet Room Vestibule nsible: Karen Clower, ee: No Restrooms Sign - 12" Circle/Triang No 12" triangle superir ces: CBC 11B-703.7.2.6 Required sign not prov	Interim ADA Coordinat Paragraph: M.51 Remedi tle at Unisex Restroom mposed on 12" circle pr	Dwg: N/A fation: Required ovided on door or ng to toilet room		
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed	Toilet Room Vestibule nsible: Karen Clower, ee: No Restrooms Sign - 12" Circle/Triang No 12" triangle superir ces: CBC 11B-703.7.2.6 Required sign not prov	Interim ADA Coordinat Paragraph: M.51 Remedi tle at Unisex Restroom mposed on 12" circle process 6.3 ided on doorway leadin	Dwg: N/A fation: Required ovided on door or ng to toilet room		
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed Solution:	Toilet Room Vestibule nsible: Karen Clower, ee: No Restrooms Sign - 12" Circle/Triang No 12" triangle superir ces: CBC 11B-703.7.2.6 Required sign not prov Provide 12" circle/triang	Interim ADA Coordinat Paragraph: M.51 Remedi gle at Unisex Restroom mposed on 12" circle proceed. 5.3 ided on doorway leading	Dwg: N/A fation: Required ovided on door or ng to toilet room orway \$250.00	doorway to unisex toilet room	
Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed Solution: As-Built Meas	Toilet Room Vestibule nsible: Karen Clower, ee: No Restrooms Sign - 12" Circle/Triang No 12" triangle superir ces: CBC 11B-703.7.2.6 Required sign not prov Provide 12" circle/triang : 1 Quantity: N/A	Interim ADA Coordinat Paragraph: M.51 Remedi Remedi Remedi Restroom Remedi Remedi Remedi Remedi Remedi Remedi Remedi Remedi Remedi	Dwg: N/A fation: Required ovided on door or ng to toilet room orway \$250.00	doorway to unisex toilet room BSR: 1 Necessary	



Field Date:	2/28/2019 Repo	rt Date: 3/8/2019	Barrier #: 4C	
Facility:	3156 Redwood Drive,	Redway		
Location:	Toilet Room Vestibule			
Official Respo	nsible: Karen Clower	, Interim ADA Coordinato	or	
Consent Decr	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Doors or Gates	Remedia	tion: Required	
Barrier Type:	Maneuvering CI - Int Fi	ront App/Pull 18"		
Barrier Description:	Door/Gate at pull side	lacks min. 18" beyond la	tch side of door	
Code Referen	ces: CBC Figure 11B-40	04.2.4.1 and 2010 ADAS	404.2.4.1	
As Built Description:	2" maneuvering cleara room	nce at pull side of door o	lue to structural	support at exit side from toilet
Proposed Solution:	Relocate door or gate	or alter area to provide r	equired maneuv	vering clearance
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$2,250.00	BSR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z	Coordinate: N/A
Implementation	on: Priority 2	Phase	Date	Status Open
Notes:				
Field Date:	2/28/2019 Repor	rt Date: 3/8/2019	Barrier #: 4D	
Facility:	3156 Redwood Drive, I	Redway		
Location:	Toilet Room Vestibule			
Official Respo	nsible: Karen Clower,	Interim ADA Coordinato	or	
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Controls and Mechanis	sms Remedia	tion: Required	
Barrier Type:	Electrical Switches - Sig	de Reach High Unobstruc	ted	
Barrier Description:	Light switch control bo	x not max. 48" high mea	sured to the top	of the outlet box
Code Referen	ces: CBC 11B-308.1.1,	11B-308.3.1 and 2010 AI	DAS 308.3	
As Built Description:	48-1/3" high			
Proposed Solution:	Relocate switch box to	max. 48" high measured	d to the top of th	e outlet box
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$750.00	BSR: 3 Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	Z	Coordinate: N/A
Implementation	on: Priority 2	Phase	Date	Status Open
Notes:				



Field Date:	2/28/2019 Repo	rt Date: 3/8/2019	Barrier #: 4E	10 1	
Facility:	3156 Redwood Drive, Redway				
Location:	Toilet Room Vestibule				
Official Respo	nsible: Karen Clower	, Interim ADA Coordinato	r		
Consent Decr	ee: No	Paragraph: M.51	Dwg: N/A		
Barrier Area:	Accessible Route - Inte	rior Remedia	tion: Required		
Barrier Type:	Accessible Route - Eler	nent (Stored Items)	**		
Barrier Description:	No accessible route pr	ovided to element requir	ed to be accessible		
Code Referen	ces: CBC 11B-206.2.4	& 11B-305.6 and 2010 AD	PAS 206.2.4 & 305.6		
As Built Description:		rovided due to stored ite		- I	
Proposed Solution:	Remove or relocate st	ored items		-	
As-Built Meas	: 0 Quantity:	JOB Cost Estimate:	\$0.00 BSR:	1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordina	ate: N/A	
Implementati	on: Priority 2	Phase	Date	Status Open	
Notes:	=				
Field Date:	2/28/2019 Repor	t Date: 3/8/2019	Barrier #: 5A		
Facility:	3156 Redwood Drive,	Redway			
Location:	Toilet Room			100	
Official Respo	nsible: Karen Clower,	Interim ADA Coordinato	r		
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A		
Barrier Area:	Restrooms	Remediat	ion: Required		
Barrier Type:	Sign - 12" Circle/Triang	le at Unisex Restroom			
Barrier Description:	No 12" triangle superir	nposed on 12" circle prov	vided on door or doorwa	y to unisex toilet room	
Code Referen	ces: CBC 11B-703.7.2.6	i.3			
As Built Description:	Required sign not prov	ided on door or doorway			
Proposed Solution:	Provide 12" circle/triar	gle sign on door or door	way		
As-Built Meas	Quantity:	EACH Cost Estimate:	\$250.00 BSR:	1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordina	te: N/A	
Implementation	on: Priority 3	Phase	Date	Status Open	
Notes:					
1					

Field Date:	2/28/2019 Repo	rt Date: 3/8/2019	Barrier #: 5	В
Facility:	3156 Redwood Drive,	Redway		
Location:	Toilet Room			70
Official Respo	onsible: Karen Clower	, Interim ADA Coordinate	or	
Consent Decr	ree: No	Paragraph: M.51	Dwg: N	'A
Barrier Area:	Restrooms	Remedia	ation: Required	
Barrier Type:	Sign - Braille/tactile In	formation		
Barrier Description:	No sign with Braille/Ta	ctile information provid	ed to identify re	estroom
Code Referer	ces: CBC 11B-216.2 an	d 2010 ADAS 216.2		
As Built Description:	No tactile information	at wall on latch side of o	door	1
Proposed Solution:	Move existing sign or p	provide new sign		
As-Built Meas	s: 1 Quantity:	EACH Cost Estimate:	\$250.00	BSR: 1 Necessary
X Coordinate	: N/A	Y Coordinate: N/A	7	Coordinate: N/A
Implementati	ion: Priority 3	Phase	Date	Status Open
Notes:				
Field Date:	2/28/2019 Repo	rt Date: 3/8/2019	Barrier #: 50	
Facility:	3156 Redwood Drive,	Redway		
Location:	Toilet Room			
Official Respo	onsible: Karen Clower	, Interim ADA Coordinato	or	
Consent Decr	ee: No	Paragraph: M.51	Dwg: N/	A
Barrier Area:	Controls and Mechanis	sms Remedia	ation: Required	
Barrier Type:	Electrical Switches - Sig	de Reach High Unobstruc	cted	
Barrier Description:	Light switch control bo	ox not max. 48" high mea	asured to the to	p of the outlet box
Code Referen	ces: CBC 11B-308.1.1,	11B-308.3.1 and 2010 A	DAS 308.3	
As Built Description:	48-1/3" high			
Proposed Solution:	Relocate switch box to	max. 48" high measured	d to the top of t	he outlet box
As-Built Meas	c: 1 Quantity:	EACH Cost Estimate:	\$750.00	BSR: 3 Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	Z	Coordinate: N/A
Implementati	on: Priority 3	Phase	Date	Status Open
Notes:				





LI TOII TEEI (III TO	•			
Field Date:	2/28/2019 Rep	ort Date: 3/8/2019	Barrier #:	5D
Facility:	3156 Redwood Drive	, Redway		
Location:	Toilet Room			476
Official Respo	nsible: Karen Clowe	r, Interim ADA Coordir	nator	Dec.
Consent Decr	ee: No	Paragraph: M.51	Dwg:	N/A
Barrier Area:	Restrooms	Reme	ediation: Requi	red
Barrier Type:	Dispensers - Control	Point		
Barrier Description:	Dispenser control po	nt or operating mecha	ınism not max. 4	IO" AFF
Code Referen	ces: CBC 11B-603.5			
As Built Description:	49" high control poin	t at paper towel disper	nser	
Proposed Solution:	Replace or remount o	lispenser		
As-Built Meas	: 1 Quantity	EACH Cost Estima	te: \$125.00	BSR: 2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A		Z Coordinate: N/A
Implementati	on: Priority 3	Phase	Date	Status Open
Notes:				
Field Date:	2/28/2019 Repo	ort Date: 3/8/2019	Barrier #:	SE
Facility:	3156 Redwood Drive	Redway		
Location:	Toilet Room			0~
Official Respo	nsible: Karen Clowe	r, Interim ADA Coordir	nator	THE RESERVE OF THE PERSON OF T
Consent Decr	ee: No	Paragraph: M.51	Dwg:	N/A
Barrier Area:	Restrooms	Reme	ediation: Requi	red
Barrier Type:	Dispensers - Protrudi	ng Object		
Barrier Description:	Dispenser creates pro	truding object in path	of travel	
Code Referen	ces: CBC 11B-307.2 a	nd 2010 ADAS 307.2		
As Built Description:	Paper towel dispense	r protrudes 9-1/2" at 4	19" high in acces	sible route to lavatory
Proposed Solution:	Relocate/remount dis	penser or provide det	ectable warning	
As-Built Meas	: 0 Quantity:	EACH Cost Estimat	te: \$0.00	BSR: 2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A		Z Coordinate: N/A
Implementati	on: Priority 3	Phase	Date	Status Open
Notes:				



Field Date:	2/28/2019 Repo	rt Date: 3/8/2019	Barrier #: SF	
Facility:	3156 Redwood Drive,	Redway		>
Location:	Toilet Room		/	
Official Respo	nsible: Karen Clower	, Interim ADA Coordinato	or 🏻 📗	
Consent Decre	ee: No	Paragraph: M.51	Dwg: N/A	
Barrier Area:	Restrooms	Remedia	tion: Required	
Barrier Type:	WC - Flush Controls Lo	cation		
Barrier Description:	Flush controls does no	t point to wide side of st	all or compartment	
Code Referen	ces: CBC 11B-604.6 an	d 2010 ADAS 604.6		
As Built Description:	Flush controls points to	owards wall or partition		
Proposed Solution:	Replace tank to provid	e min. one accessible wa	ter closet	
As-Built Meas	Quantity:	JOB Cost Estimate:	\$850.00 BSR: 1	. Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinat	e: N/A
Implementation	on: Priority 3	Phase	Date	Status Open
Notes:				

BARRIER DATA RECORDS

COST ESTIMATES



SUMMARY REPORT

Cost Estimate Total	\$16,340.00		
Cost Estimate - Priority 1:	\$1,200.00	% of Total Cost Estimate:	7.34%
Cost Estimate - Priority 2:	\$11,915.00	% of Total Cost Estimate:	72.92%
Cost Estimate - Priority 3:	\$2,225.00	% of Total Cost Estimate:	13.62%
Cost Estimate - Priority 4:	\$1,000.00	% of Total Cost Estimate:	6.12%