SZS ENGINEERING ACCESS



COUNTY OF HUMBOLDT, CALIFORNIA

PUBLIC HEALTH MCAH

ADA ACCESS COMPLIANCE ASSESSMENT

317 2nd STREET, EUREKA CA (COUNTY LEASED FACILITY)



Sacramento Office 770 L Street, Suite 950 Sacramento, CA 95814 Email: Info@szs.engineering

Tel: 916.669.8750 Fax: 888.211.7441

Silicon Valley Office 2225 E. Bayshore Road, Suite 200

Palo Alto CA 94303 Tel: 866.694.7637 www.szs.engineering

January 16, 2020



Humboldt County Administrative Office CAO-ADA Compliance Team 825 Fifth Street, Room 112 Eureka, California 95501 Attention: Karen Clower, ADA Coordinator

Re: PUBLIC HEALTH MCAH – ADA ACCESS COMPLIANCE ASSESSMENT

Dear Ms. Clower,

We are pleased to submit this report as a first step in the process to identify barriers to access for the County of Humboldt. This process will allow the County to apply programmatic accessibility before resorting to physical barrier removal, in order to conserve funds while meeting the goal of improving access.

This has been an informative process. We look forward to creating an updated digital remediation program to facilitate implementation. Please review the report and provide input. We welcome collaboration in this process.

Contact me with any questions you may have.

Regards,

Syroun Z. Sanossian, Principal

Syn Z. Sm.

SZS Engineering Access, Inc.



TABLE OF CONTENTS

1.	EXECUTIV	VE SUMMARY	p. 1
	A.	Private Entities, Public Accommodations and the ADA	p. 3
	В.	Safe Harbor Provisions	p. 7
	C.	Barrier Severity Ratings and Remediation	p. 8
	D.	Official Responsible	p. 9
	E.	Recommended Barrier Removal Priorities	p. 9
	F.	Cost Estimates	p. 11
	G.	Exterior Spaces	p. 11
	Н.	Facility Entrances	p. 12
	I.	Report Format Definitions	p. 13
2.	EXTERIO	R SPACES	p. 16
3.	INTERIOR	? SPACES	p. 16
4.	BARRIER	DATA RECORDS	
	A.	Barrier Data Records	p. 18
	В.	Cost Estimate	p. 57
5.	APPENDI	x	
	Α.	Reference Drawings	p. 58



1. EXECUTIVE SUMMARY

This ADA Access Compliance Assessment was compiled for the Public Health MCAH facility located at 317 2nd Street in Eureka, CA. This structure is leased by the County of Humboldt as a location where the County can provide county programs, services and activities. As a privately owned facility in which public activities take place, the facility is defined under the ADA as a public accommodation.

This report was developed to fulfill requirements under the consent decree entered into by the County of Humboldt with the US Department of Justice (DOJ). The United States alleged that Humboldt County has discriminated, and continues to discriminate, against individuals with disabilities by failing to make County facilities, programs, services, and activities accessible to and useable by individuals with disabilities in violation of the ADA.

The DOJ initiated a compliance review of Humboldt County under its Project Civic Access ("PCA") initiative, a wide-ranging effort to ensure that cities, counties, and other public entities throughout the country comply with the ADA by eliminating physical, communication, and other barriers that prevent people with disabilities from participating fully in community life. The DOJ's review of the County included a review of its programs and an accessibility survey of over 50 facilities, although the consent decree governs all facilities in which County programs, services or activities take place¹. As the result of its review, the Department found numerous violations of the ADA, notified the County of the violations and negotiated a settlement agreement in which the County committed to bring its facilities, programs, services and activities into compliance with the ADA.

SZS Engineering Access, Inc. is the Independent Licensed Architect ("ILA"), pre-approved by the DOJ, acting independently to certify whether any alterations, additions, or modifications made by the County during the term of this Consent Decree comply with the applicable standard pursuant to 28 C.F.R. § 35.151(c) and the Appendix to 28 C.F.R. § 35.151(c)².

In issuing certifications pursuant to this Consent Decree, the ILA will impartially prepare reports identifying each violation and demonstrating with photographs each violation that has been remediated. The ILA is considered a neutral inspector for purposes of issuing certifications of compliance.

Under the consent decree, the County agreed not to deny the benefits of its programs, services, and activities³ or discriminate against individuals with a disability, and will not, based on disability provide an unequal, different, or separate opportunity to participate in its programs, services, and activities⁴.

The intent of this assessment report is to identify physical barriers to access, so that design professionals can use the information to ensure that alterations to facilities that house County programs, services and activities result in facilities that are accessible to and usable by people with disabilities. This facility is owned by a private party. Where the owner leases the facility for use as a public accommodation, the facility must comply with requirements to provide access

-

¹ US v. County of Humboldt, US v. County of Humboldt, Civil Action No. 16-5139, Attachment - G, H, I, J

² 28 C.F.R. § 35.151(c) and the Appendix to 28 C.F.R. § 35.151(c)

³ 28 C.F.R. § 35.130(b)(1).

⁴ 28 C.F.R. § 35.130(b)(1), (3).



to a public accommodation. If the County were to vacate this facility, the requirements will remain in place for any other parties leasing the facility that provide public accommodations.

The field investigation began on June 29, 2017. Images of each physical element identified in this report were captured in HD digital photos while manual measurements were taken to establish as-built conditions for the process of cost estimating. Digital photographs are provided within this report for each barrier to access to facilitate the review of the data collected. Technical data can be interpreted more efficiently with a visual component; the photos provide a clear connection between the technical data described in each barrier data record and the physical barrier to access identified.

When taking measurements in exterior areas, visual markers are used to indicate the location or beginning and end of a barrier such as a cross slope. Red cups or the digital level used to take measurements will be used in photos as a visual marker to indicate the location of these exterior barriers within the context of the existing site conditions.

The Public Health MCAH facility is a structure that was built before the enforcement of the Americans with Disabilities Act and barriers to access were identified.

ADA Title III holds that no individual shall be discriminated against on the basis of disability in the full and equal enjoyment of the goods, services, facilities, privileges, advantages, or accommodations of any place of public accommodation by any private entity who owns, leases (or leases to), or operates a place of public accommodation. The findings presented are both narrative and technical in nature. Physical barriers to access identified during the field investigation process are documented in two ways:

- 1. <u>Summary and Analysis:</u> An analysis of findings is provided in a narrative form that describes particular barriers identified in the following records to help ensure that the findings for atypical situations can be further explained. The intent of this information is to provide a discussion on the functionality of physical elements. Background reasoning and research behind the identification of barriers is also provided where universal design principles may play a role. This analysis may be accompanied by digital photographs or diagrams, where applicable. Understanding building function and usage is essential when interpreting the findings held in this report. The narrative is intended to facilitate this process.
- 2. <u>Barrier Data Records:</u> Individual barriers to access are entered into the ADA/Access Compliance database so that technical information on each individual barrier can be provided a barrier data record. These barrier data records include detailed information including digital photographs of each barrier identified, code references that determine the barrier to access, as-built measurements, barrier severity ratings, budgetary cost estimates, recommended solutions for barrier removal and a priority for barrier removal will be assigned in the final report. The information is formatted with two barriers on each report page.

Each barrier identified in this report is designated as either required for removal or recommended for removal. State and federal model code provide the basis for most of the barrier identification contained in this report. There are other barriers to access that are dictated by case law precedent, vehicle code, health code, safety code and labor code. Most barriers identified in this report are based on those requirements but additional barriers exist



that are not based on these regulations or statutes. Barriers that are recommended for removal are based on pending regulations or good practices. The associated field provides two options for each barrier: Required or Recommended.

It is important to note that the barriers identified in this report reflect the most stringent requirements from the 2010 ADA Standards, California Code of Regulations/Title 24 and the California edition of the Manual on Uniform Traffic Control Devices (MUTCD). These model codes are not identical and contain conflicting requirements. To ensure ADA Access Compliance is achieved, this report is based on the most stringent requirements taken from these model codes.

In order to consolidate the barrier data, some of the more typical barriers found in multiple locations have been grouped within the barrier data records with a description of the locations in which they were found. For instance, this occurs where barriers were identified in stairways that have existing handrails that continue through multiple floors.

A. PRIVATE ENTITIES, PUBLIC ACCOMMODATIONS AND THE ADA

The landmark Americans with Disabilities Act (ADA), enacted on July 26, 1990 provides comprehensive civil rights protection to individuals with disabilities in the many areas including employment, telecommunications, facilities that offer public accommodations, and state and local governmental services. The ADA is comprised of five parts, or titles. Each title covers a specific area delineated by the ADA, in which the legislation is intended to enhance accessibility for persons with disabilities. The five titles are as follows:

<u>Title I:</u> Employment Practices by units of State and Local Governments

Title II: Programs, Services and Activities of State and Local Governments

<u>Title III:</u> Public Accommodations and Commercial Facilities (private businesses and non-profit service providers)

Title IV: Telecommunications

Title V: Miscellaneous Provisions

Title III of the Americans with Disabilities Act of 1990 (42 U.S.C. 12181) applies to this property. Title III prohibits discrimination on the basis of disability by public accommodations and requires places of public accommodation and commercial facilities to be designed, constructed, and altered in compliance with the construction-related accessibility standards established by Section 36.101 of the Act. The 2010 ADA Standards have updated the original ADA as of March 2012.

Furthermore, ADA Title III holds that no individual shall be discriminated against on the basis of disability in the full and equal enjoyment of the goods, services, facilities, privileges, advantages, or accommodations of any place of public accommodation by any private entity who owns, leases (or leases to), or operates a place of public accommodation. Both the landlord who owns the site that houses a place of public accommodation and the tenant who owns or operates the place of public accommodation are responsible to provide accessible public accommodations subject to the requirements of this Title. As between the parties, allocation of



responsibility for complying with the obligations of this part may be determined by lease or other contract.⁵ The terms of the lease should define the responsibilities.

ACTIVITIES

Public accommodations also cannot deny participation to persons with disabilities, or provide for unequal or separate benefits for persons with disabilities. The basis of the ADA is the integration of persons with disabilities into society, not the expectation of preference or any type of special treatment.

A public accommodation shall afford goods, services, facilities, privileges, advantages, and accommodations to an individual with a disability in the most integrated setting appropriate to the needs of the individual. The maintenance of accessible features is essential. A public accommodation shall maintain in operable working condition those features of facilities and equipment that are required to be readily accessible to and usable by persons with disabilities by the Act, although this Act or section does not prohibit isolated or temporary interruptions in service or access due to maintenance or repairs.

ELIGIBILITY CRITERIA

A public accommodation shall not impose or apply eligibility criteria that screen out or tend to screen out an individual with a disability or any class of individuals with disabilities from fully and equally enjoying any goods, services, facilities, privileges, advantages, or accommodations, unless such criteria can be shown to be necessary for the provision of the goods, services, facilities, privileges, advantages, or accommodations being offered. But, a public accommodation may impose legitimate safety requirements that are necessary for safe operation. Safety requirements must be based on actual risks and not on mere speculation, stereotypes, or generalizations about individuals with disabilities. A public accommodation also may not impose a surcharge on a particular individual with a disability or any group of individuals with disabilities to cover the costs of measures, such as the provision of auxiliary aids, barrier removal, alternatives to barrier removal, and reasonable modifications in policies, practices, or procedures, that are required to provide that individual or group with the nondiscriminatory treatment required by the Act or this section.

MODIFICATIONS IN POLICIES, PRACTICES OR PROCEDURES

A public accommodation shall make reasonable modifications in policies, practices, or procedures, when the modifications are necessary to afford goods, services, facilities, privileges, advantages, or accommodations to individuals with disabilities, unless the public accommodation can demonstrate that making the modifications would fundamentally alter the nature of the goods, services, facilities, privileges, advantages, or accommodations. This is significant in terms of physical alterations made to improve accessibility for persons with disabilities. A public accommodation may refer an individual with a disability to another public accommodation, if that individual is seeking, or requires, treatment or services outside of the referring public accommodation's area of specialization, and if, in the normal

⁵ Department of Justice ADA Title III Regulations 28 CFR Part 36; Sec.36.105 -- 36.199 [Reserved] Subpart B -- General Requirements Sec.36.201 General. (b)



course of its operations, the referring public accommodation would make a similar referral for an individual without a disability who seeks or requires the same treatment or services.

AUXILIARY AIDS AND SERVICES

A public accommodation shall take steps that may be necessary to ensure that no individual with a disability is excluded, denied services, segregated or otherwise treated differently than other individuals because of the absence of auxiliary aids and services, unless the public accommodation can demonstrate that taking those steps would fundamentally alter the nature of the goods, services, facilities, privileges, advantages, or accommodations being offered or would result in an undue burden, i.e., significant difficulty or expense.

REMOVAL OF BARRIERS

A public accommodation shall remove architectural barriers in <u>existing facilities</u>, including communication barriers that are structural in nature, where design and construction for first occupancy started before January 26, 1993, and such removal is readily achievable, i.e., easily accomplishable and able to be carried out without much difficulty or expense⁶. Examples of steps to remove barriers include, but are not limited to, the following actions:

- 1) Installing ramps;
- 2) Making curb cuts in sidewalks and entrances;
- 3) Repositioning shelves;
- 4) Rearranging tables, chairs, vending machines, display racks, and other furniture;
- 5) Repositioning telephones;
- 6) Adding raised markings on elevator control buttons;
- 7) Installing flashing alarm lights;
- 8) Widening doors;
- 9) Installing offset hinges to widen doorways;
- 10) Eliminating a turnstile or providing an alternative accessible path;
- 11) Installing accessible door hardware;
- 12) Installing grab bars in toilet stalls;
- 13) Rearranging toilet partitions to increase maneuvering space;
- 14) Insulating lavatory pipes under sinks to prevent burns;
- 15) Installing a raised toilet seat;
- 16) Installing a full-length bathroom mirror;
- 17) Repositioning the paper towel dispenser in a bathroom;
- 18) Creating designated accessible parking spaces;

SZS ENGINEERING

7

⁶ Department of Justice ADA Title III Regulations 28 CFR Part 36; Sec..36.105 -- 36.199 [Reserved] Subpart B -- General Requirements Sec.36.304 Removal of barriers.



- 19) Installing an accessible paper cup dispenser at an existing inaccessible water fountain;
- 20) Removing high pile, low density carpeting; or
- 21) Installing vehicle hand controls.

PRIORITIES

It is recommended that a public accommodation take measures to comply with the barrier removal requirements of this section in accordance with the following order of priorities:

- (1) A public accommodation should take measures to provide access to a place of public accommodation from public sidewalks, parking, or public transportation. These measures include, for example, installing an entrance ramp, widening entrances, and providing accessible parking spaces.
- (2) Second, a public accommodation should take measures to provide access to those areas of a place of public accommodation where goods and services are made available to the public. These measures include, for example, adjusting the layout of display racks, rearranging tables, providing Brailled and raised character signage, widening doors, providing visual alarms, and installing ramps.
- (3) Third, a public accommodation should take measures to provide access to restroom facilities. These measures include, for example, removal of obstructing furniture or vending machines, widening of doors, installation of ramps, providing accessible signage, widening of toilet stalls, and installation of grab bars.
- (4) Fourth, a public accommodation should take any other measures necessary to provide access to the goods, services, facilities, privileges, advantages, or accommodations of a place of public accommodation. This may include providing space in the seating area for wheelchair users to maneuver or wait, as able-bodied persons presently do.

No measure shall be taken; however, that poses a significant risk to the health or safety of individuals with disabilities or others. The provision of visual alarms is only required in sites where existing fire alarm systems are provided.

ALTERNATIVES TO BARRIER REMOVAL

Where a public accommodation cannot demonstrate that barrier removal is readily achievable, the public accommodation shall make its goods, services, facilities, privileges, advantages, or accommodations available through alternative methods, if those methods are readily achievable. Examples of alternatives to barrier removal include, but are not limited to, the following:

- (1) Providing curb service or home delivery;
- (2) Retrieving merchandise from inaccessible shelves or racks; and
- (3) Relocating activities to accessible locations.



Accessibility improvements for existing facilities must be viewed on a case-by-case basis; especially where space constraints or other extenuating circumstances may exist. Further, there may be instances where alterations that are otherwise necessary to provide fully compliant accessibility may be technically infeasible. In such cases, it is expected that alterations aimed at full compliance be made to the maximum extent feasible.

What does "maximum extent feasible" mean? In the context of ADA compliance, the "maximum extent feasible" refers to the greatest degree of alterations that can be made to existing sites and structures without adversely affecting:

- (1) the structural integrity of the site or structure;
- (2) the historical fabric of the site or structure; or
- (3) the naturally occurring geographic barriers surrounding the site or structure.

The fact that adding accessibility features during an alteration may increase costs does not, by itself, mean compliance is technically infeasible. Moreover, even if it is technically infeasible to comply with standards for individuals with certain disabilities (for instance, those who use wheelchairs), the alteration must still comply with standards for individuals with other impairments.⁷

ILLUSTRATION 1: A restaurant is undergoing a major renovation. Widening the entrance would affect the site structure because removal of an essential part of the structural frame would be required. In this case, it is "technically infeasible" to widen the entrance and the alteration is not required. However, all other CBC/ADA alterations requirements would apply to the renovation.

BUT: If the only problem with widening the entrance is that it would increase the cost of the renovation, the "technically infeasible" exception does not apply, and the entrance must be widened.

These issues have been taken into consideration while compiling this report. In cases where a facility was constructed since the enforcement of the ADA, full compliance is required.

B. SAFE HARBOR PROVISIONS

The County of Humboldt and private property owners can make use of the *safe harbor* provision contained in the 2010 ADA Standards. This federal rule applies to provisions in the ADA Standards and is applied on an element-by-element basis for elements that complied with the 1991 ADA Standards. The rule includes a general "safe harbor" under which physical elements in facilities used for County programs, activities and services, that were built or altered in compliance with the 1991 Standards, would not be required to be brought into compliance with the 2010 Standards until the elements were subject to a planned alteration. A similar safe harbor applies to elements associated with the "path of travel" to an altered area. The federal Access Board has provided a list of the new

Department of Justice: Americans with Disabilities Act ADA Title III Technical Assistance Manual Covering Public Accommodations and Commercial Facilities. III-6.1000 General.



requirements in the 2010 Standards that are not eligible for the safe harbor in § 35.150(b)(2)(ii)(A) through § 35.150(b)(2)(ii)(L) of the final rule⁸, which includes golf courses, recreation areas, play areas outdoor recreational areas and open spaces not originally covered by the 1990 Standards that are now included in the 2010 Standards.

The most common area where safe harbor applies in this particular facility is within the reach range requirements. Previous requirements under the 1990 ADA Standards allowed high reach range to extend to a maximum of 54 inches high, whereas the 2010 ADA Standards now allow a maximum reach of only 48 inches. Many controls and mechanisms can be granted safe harbor under this federal provision. Safe harbor does not apply to areas where an alteration to the permanent room or space has been performed since 1992, which required the element (e.g. light switch) to comply with the new construction standards in place at the time of the alteration.

C. BARRIER SEVERITY RATINGS AND REMEDIATION

SZS has developed proprietary barrier identification systems to standardize our process and ensure consistency while collecting data, creating reports and recommending implementation removal over time. Our proprietary barrier severity rating system was developed through many years of research and experience, and is integrated into our database, so that each barrier is assigned a rating that defines how severely each barrier affects a person's ability to use the element. We know from experience that without a systematic approach to barrier severity rating, deciding which barriers to remove, and when, can be reduced to guesswork.

There are five barrier severity ratings (BSR) that are assigned to individual barriers:

- 1 Necessary
- 2 Recommended
- 3 Hindrance
- 4 Low Severity
- 5 Technically Infeasible

The affect that the barrier has on a person using the element is important, but the date of construction also plays a role in determining barrier severity ratings. Facilities that are defined under the ADA as new construction are required to be fully compliant and the barrier severity rating assigned to those barriers is 1 – Necessary to Remove. That is a legal requirement that governs our work regardless of how minor a barrier may be in terms of how it affects the user.

In existing facilities, which were constructed prior to the passage of the ADA, barrier removal is not required to achieve new construction standards. The standard for barrier removal is to bring a facility into compliance to the maximum extent feasible. This standard takes into consideration past building standards and practices which did not comply to the current ADA standards. Where barrier severity ratings are 4- Low Severity, these barriers may not require remediation. When barriers are rated as a 5 – Technically Infeasible, they

⁸ Americans with Disabilities Act Title II Regulations, Part 35 Nondiscrimination on the Basis of Disability in State and Local Government Services (as amended by the final rule published on September 15, 2010) http://www.ada.gov/regs2010/titleII_2010/titleII_2010_regulations.htm



cannot be removed due to structural impracticability or other conditions that cannot be altered. Increasing the clear width of an interior stairway in an existing building, or reducing the roadway slope where it corresponds with steep terrain, is technically infeasible to remediate.

Sidewalks, which were constructed prior to 1992, were often constructed intentionally with a cross slope to encourage drainage that is now defined as a code violation. Research shows that the affect that the cross slope of a walking surface between 2.1% and 2.9% is minor, or of a low severity, and can be navigated by a person using a mobility assist device with some extra effort, whereas a cross slope of 5.0% or more is known to cause a wheelchair to tip over which may result in injury. Existing walkways and sidewalks that are identified with a cross slope in the 2.1% and 2.9% range are assigned a low severity BSR with remediation not generally recommended where the duration (linear footage) of the barrier is limited to less than 5 feet and the affect they have for people using mobility assist devices is minor in comparison to many other barriers identified. Other instances where barriers are identified in the report and no remediation is recommended will be provided with an explanation on a case-by-case basis.

Barriers with a low severity rating are often assigned a Proposed Solution of "No remediation recommended – low severity barrier". The California Division of State Architect has approved this approach for projects throughout the state, since it is reasonable and allows for funds to be concentrated on barrier removals that have hindered or prevented use of an element by people with disabilities.

D. OFFICIAL RESPONSIBLE

The County of Humboldt is responsible to ensure access for people with disabilities to the programs, services or activities that they provide, whether they are provided in owned or leased facilities. The County is not necessarily the responsible party entrusted with removing barriers in leased facilities. The county will work with property owners, where feasible, to ensure compliance. Under the federal statute, discrimination includes a failure to design and construct facilities for first occupancy after January 26, 1993, that are readily accessible to and usable by individuals with disabilities⁹. California government code, civil code, health and safety code, vehicle code and labor code contain similar requirements.

The designated ADA Coordinator (ADA CO) is in charge of the barrier remediation plan pursuant to the Project Civic Access Consent Decree and ADA Transition Plan remediation during the time in which these reports have been compiled. The ADA CO and/or representative can be reached at (844) 365-0352 or ADA@co.humboldt.ca.us. It is likely that the person in this position will change over time through attrition, or retirement. At that time, another ADA CO will be assigned and assume these responsibilities to ensure continuity of services.

E. RECOMMENDED BARRIER REMOVAL PRIORITIES

The functions within the buildings were assigned a barrier removal priority that corresponds with the regulations discussed above. All construction and alterations to County buildings and facilities by the County or on its behalf [in leased facilities] will comply with the

⁹ Subpart D – New Construction and Alterations. § 36.401 New construction. (a) General. (a)



requirements of 28 C.F.R. § 35.151, including applicable architectural standards. All architectural changes by the County or on its behalf made on or after March 15, 2012, must comply with the 2010 ADA Standards. The term "2010 ADA Standards" refers to the 2010 ADA Standards for Accessible Design (28 C.F.R. § 35.104 (Title II) (defining the "2010 ADA Standards" as the requirements set forth in appendices B and D to 36 C.F.R. part 1191 and the requirements contained in 28 C.F.R. § 35.151.)). All citations are to the 2010 ADA Standards unless otherwise noted.

The parts of a County facility that do not comply with the 1991 ADA Standards (or the 2010 ADA Standards, as applicable), as listed in Attachments G, H, I, and J, of the consent decree, prevent people with disabilities from fully and equally enjoying the County's programs, services, or activities and constitute discrimination on the basis of disability within the meaning of 42 U.S.C. § 12132 and 28 C.F.R. §§ 35.149-35.15110.

Facilities that are privately owned will remain under this consent decree whether or not the County continues to lease the facility to house programs, services and activities. As long as public accommodations continue to be provided in the facility, the requirement to remove barriers to access will remain in effect.

In addition, barrier removal priorities should reflect the way in which people use the facilities. For instance, if barrier removal is not completed and a person cannot reach the facility because there is no pedestrian access route from the public transportation provided to serve the building, or no accessible parking is provided, an accessible toilet room inside the building is of little use to people with disabilities.

In order to prioritize barrier removal within facilities for implementation we have correlated the County programs, activities and services that take place within buildings that serve people with disabilities with the barriers to access that have been identified. Barriers to access identified in the exterior and interior spaces have been prioritized according to the following criteria:

- **Priority 1**: Pedestrian route including access to the building from points of arrival and from the building site, including walkways and breezeways and potential hazards (see stairways below). Building entrances and lobby spaces
- **Priority 2**: Primary building functions (classrooms, meeting rooms, auditoriums, corridors, play areas, etc.)
- **Priority 3**: Restrooms, drinking fountains and benches or tables in public places
- **Priority 4**: Interior and exterior stairways, signage and remaining barriers that affect people with disabilities as a low severity barrier

Finalized barrier priorities can be influenced by information on other factors provided by the County of Humboldt. These factors include:

_

¹⁰ US v. County of Humboldt, Civil Action No. 16-5139, Section II.M: New Construction, Alterations, and Physical Changes to Facilities.



- Number and type of programs, services and activities that take place in the facility
- Frequency of use by the general public
- Age of facility (pre-1992 existing or new construction post-1992)
- Type of use (public, staff or mixed use)
- Long-term Facility Planning Goals
 - Infrastructure improvement projects
 - Facility replacement as part of future CIP plans

F. COST ESTIMATES

This report contains budgetary cost estimates provided to facilitate the remediation of barriers. Cost estimates are provided for physical elements only while the cost of implementing a new policy or practice cannot be accurately assessed at this point in the process. The actual cost estimates are calculated using RS Means Construction Cost Estimating data and in some instances where a barrier location can have several different barriers to access, one or more of the barriers may have a cost estimate of \$0 dollars. This is an intentional reporting mechanism as it reflects the fact that the cost to remove that particular barrier is part of a cost of one or more barriers at that same location.

For instance, where a door equipped with a door closer is identified with a non-compliant opening force, sweep period and a lack of required maneuvering clearance on one or both sides of that door, the recommended barrier removal solution is often to install an automatic door opening device (ADOD), which at the time of this assessment is estimated to cost \$5,000. If each of those barriers to access had been reported with a cost estimate, the estimate could amount to 3 times that much, or \$15,000 if the correction to 2 of the 3 cost estimates was not performed. The end result is intended to produce a budgetary cost estimate that does not include amounts that could exponentially increase the overall cost of barrier removal implementation plans.

G. EXTERIOR SPACES

This assessment process included identification of barriers to access within the pedestrian access route (accessible route within the public rights-of-way or PROW) that serves this facility. Under state and federal regulations and statutes, the pedestrian access route from points of arrival at public transportation stops (where provided), continuing through sidewalks (where provided) and walkways leading to the facility entrance must be accessible to people with disabilities in order to ensure that they can reach the facility where programs, services and activities are provided. This information is not contained in this report, but has been compiled into a separate report provided to each jurisdictional authority that owns the PROW that connects bus stops and sidewalks to this facility.

Where these jurisdictions make use of federal funding for roadway work, etc. the entity is required under the federal Rehabilitation Act of 1973 to ensure that the pedestrian access route is usable by and accessible to people with disabilities. The 1990 ADA Standards



provided additional requirements intended to ensure that these paths of travel are made fully accessible "as expeditiously as possible, but, in any event, by January 26, 1995". 11

At present, barriers were identified that appeared to be pre-ADA in some cases and these entities should be making progress on this work through a Rehabilitation Act Transition Plan since 1974 or ADA Transition Plan since 1992. If such plans are not in place, this information will be provided available to these entities, to allow them to make use of it when updating their existing remediation plans to comply with state and federal statutes and regulations.

This report contains barriers to access that are located within the facility site. There may be some overlap between site arrival points and a pedestrian connection to the facility entrance. In cases where the existing sidewalk is an essential part of the accessible route to the facility entrance, alterations must be made to the sidewalk to ensure that people with disabilities can make use of County programs, services and activities.

Owners of leased properties are likely to have responsibility for some of the sidewalk that borders their property.

As a public facility that was constructed before the passage of the ADA, the facility is required to have at least one accessible entrance and an accessible route provided within the building site that connects the existing sidewalk to the exterior and interior amenities provided, including a connection to public streets and sidewalks; and public transportation stops to the accessible building or facility entrance¹², as required by the 1990 and 2010 ADA Standards and California Code of Regulations Title 24.

H. FACILITY ENTRANCES

The facility is a two-story structure with public use on the first and second floors with no form of vertical access provided. The facility makes use of off-street parking in a parking lot owned by the city of Eureka located adjacent to the building. No accessible parking is provided in the parking lot on the shortest possible route to the building entrance, although two accessible stalls are located in the opposite corner of the lot.

The building owner should contact the city and request alterations to comply including, but not limited to dispersing accessible parking to ensure that various buildings that the parking lot serves can make use of parking on the shortest possible route to the building entrance, as required by the 2010 ADA Standards 208.3.1and California Building Code CBC 11B-208.3.1.

The facility entrance is on an accessible route from the existing sidewalk, 2nd Street, in Eureka.

¹¹ The Americans with Disabilities Act, Title II Technical Assistance Manual Covering State and Local Government Programs and Services, Section II-8.3000. See https://www.ada.gov/taman2.html#II-8.3000

¹² 2010 ADA Standards for Accessible Design, Section **206.2.1 Site Arrival Points**



REPORT FORMAT - DEFINITIONS

Field Date:	8/30/2016 Repo	ort Date: 9/1	3/2016 Bar	rier#: 1	
Facility:	Jail (Adult Detention)				
Location:	Pedestrian Path to Bu	uilding			San Part Bally St.
Official Respo	nsible:			8 9	- 0
Facility Functi	on: Public			Dwg: 1 of 2	
Barrier Area:	Walkways		Remediation	Required	
Barrier Type:	Detectable Warnings	- Hazardous V	/ehicular Way		
	The second secon				
Barrier Description:	Detectable warning (1	truncated don	nes) or vertical c	urb not provided	at hazardous vehicular
Barrier Description:	Detectable warning (1 ces: CBC 11B-705.1.2		nes) or vertical c	urb not provided	at hazardous vehicular
Barrier Description:	ces: CBC 11B-705.1.2	.5	(40)		at hazardous vehicular gs installed where rod
Barrier Description: Code Referen As Built	ces: CBC 11B-705.1.2	5 g vehicular tra	ffic lane has no o	detectable warmin	gs installed where req
Barrier Description: Code Referen As Built Description: Proposed Solution:	Ces: CBC 11B-705.1.2 Pedestrian path along Provide truncated do building entry	5 g vehicular tra mes as detect	offic lane has no o	detectable warmin	gs installed where req
Barrier Description: Code Referen As Built Description: Proposed Solution:	Provide truncated do building entry	5 g vehicular tra mes as detect	ffic lane has no on the stable warning aloost Estimate: \$67	detectable warming pathway from	gs installed where roo Chestral Avenue to

This is the Graphic User Interface (GUI) for the SZS database entry form. The name of each facility is located at the top of the form and the reports produced by the database have a similar format with identical fields although they are, in some instances, slightly different in size. A description for the data contained within each field is provided below:

- 1) Field Date: The date of the facility inspection.
- 2) Report Date: The date the report was compiled, revised or completed.
- 3) Barrier #: Individual number assigned to each barrier identified. The alphanumeric character assigned correlates with a room or space identified on the reference drawings provided with each report. This number allows the barrier to be pinpointed to a location within the facility.
- **4) Image:** Digital photograph provided for each barrier as a visual representation of the issue and context.
- 5) Facility: Name of building, park or parking lot where the inspection was performed
- 6) Location: Area or space within the facility where a barrier is identified
- **7) Official Responsible:** Person responsible for overseeing the policies and practices implemented through this process



- 8) Facility Function (Public/Staff): Designates barriers as located in either staff or public areas. Most barriers identified are designated for public use. Different requirements exist for public and staff use areas.
- 9) Reference Drawing (Dwg): Floor, site plans or aerial maps of the designated facility where the assessment was performed. Each reference drawing provides correlation between the barrier number listed in the report (see item 3 above) and the actual physical location where the barrier was identified.
- **10) Barrier Area:** Provides a grouping of similar barriers identified in specific spaces (E.G.: Restrooms, Doors and Gates, Stairs, Ramps, Sidewalk, Walkways)
- **11) Remediation:** Indicates whether a barrier is in direct violation of the federal and state codes and statutes and must be remediated or whether the remediation is recommended as a best practice. One of two options exist: (Required) or (Recommended).
- **12) Barrier Type:** Identifies the type of physical element or area defined by California Building Code and the ADA Standards used to identify non-compliance. The categories of barriers contained in the database include:

Alarms
Assembly Areas
Blended Transitions
Bus Stops & Shelters
Classrooms
Clear Floor Space
Controls and Mechanisms
Corridors
Counters and Tables
Curb Ramps
Dining Facilities
Doors or Gates
Drinking Fountains
Elevators
Kitchens
Outdoor Areas Access Route
Parking
Passenger Loading Zones (Drop-Off)
Picnic Facilities
Play Areas
Public Phones
Ramps
Restrooms
Signage
Stairways
Street Furniture
Swimming Pools



Turning Space	
Walkways	

- **13) Requirement (Barrier Description):** Code language or performance standard that describes barrier identified.
- **14) Code References:** Applicable state and federal codes regulating the entities compliance. Each code reference is specific to each barrier and identifies the section of code which regulates compliance to that specific element (doors, parking stalls, sidewalks, etc.). Where a best practice is recommended, the term *Performance Standard* identifies the barrier to access documented in the barrier data record.
- **15) As Built Description (Desc):** Also known as the *findings*, information describes the barrier.
- **16) Proposed Solution:** Provides one suggested solution for the remediation of the barrier identified. Please note that other options may exist to bring items into compliance. Other solutions may exist and all solutions cannot be accounted for in this report. The suggested solution is generally the most common way of remediating this particular barrier.
- **17)** As Built Measure: Actual field measurement number for square footage (SF), linear footage (LF), or a single value (EACH or JOB) used to indicate physical dimension of barrier and calculate cost estimate.
- 18) Quantity: Unit of measure for the remediation of each barrier (SF, LF, EACH or JOB).
- **19) Cost Estimate:** Budgetary Cost Estimate to remove the barrier described.
- **20)** Barrier Severity Rating (BSR): A systematic, research based rating that describes how severely each barrier affects usability for the particular element.
- 21) X Coordinate: Geographic coordinate that provides the longitude (north-south) value
- 22) Y Coordinate: Geographic coordinate that provides the latitude (east-west) value
- 23) Z Coordinate: Geographic coordinate that provides the elevation value
- 24) Implementation Priority: N/A
- 25) Implementation Phase: N/A
- **26) Implementation Date:** Scheduled year or date as to when the remediation of the barrier will take place within the consent decree schedule. This field can be scheduled during phasing and changed to a specific date after the barrier is remediated and the record is closed.
- **27) Status (Open or Closed):** An implementation management tool that can flag barriers to indicate that they have been remediated or are remaining in the implementation phasing plan. Barrier data records have a "Closed" status when completed or have an "Open" status when they remain scheduled for remediation. This can be useful when remediation is



performed by both maintenance staff and design professionals within the construction process.

28) Notes: Open field where additional explanation of the findings can be noted when encountering unusual situations in the field, or to note programmatic access solutions. The notes field can contain the image file name shown in the barrier data record, or additional information as needed such as an explanation of findings, or information on associated barriers in the same or similar locations.

EXTERIOR SPACES

This narrative reflects the findings at the time of the original inspection. Overtime, barrier remediation has taken place and the original findings may no longer reflect present conditions.

The path of travel from the nearest bus stop was assessed as part of the scope of work. People with disabilities often travel using regional transit and must have an accessible route that allows them to reach the facility. Barriers to access were identified which may be the responsibility of another local jurisdiction to remediate. The jurisdiction should be contacted in order to ensure that these barriers are removed so that the County program, services and activities that take place in this location are accessible to people with disabilities.

Parking and a pedestrian path are provided in this location, although alterations to the existing parking and path of travel from the parking lot are required in order to ensure that people with disabilities can travel to the facility to make use of the programs, services and activities provided.

The pedestrian connection from the existing off-street parking to the building entrance requires a minimum of 1 van accessible stall on the shortest possible route to the building entrance. This would entail pedestrian travel across Snug Alley which is a vehicular traffic lane (see photo at right). The parking lot currently provides no van accessible stall, although two standard accessible stalls are provided in one location, rather than being dispersed near entrances to multiple facilities that the parking lot serves, which is a requirement for off-street parking facilities.



The walkway at the main entrance to the facility was identified with a significant cross slope, including a slope at the entrance door landing, which could hinder or prevent people who use wheelchairs from entering the facility. The installation of an automatic door opening device would not be a recommended solution, as the cross slope at the entrance door is 5.0%, which through research, has been shown to cause people who use wheelchairs to tip over.

INTERIOR SPACES


This narrative reflects the findings at the time of the original inspection. Overtime, barrier remediation has taken place and the original findings may no longer reflect present conditions.



The entrance doors were identified without signage that identifies the entrance as accessible. The entry doors did not appear to be equipped with door closer devices. The surface of the service counter was accessible in several locations, although knee clearance was 9" deep which can prevent people who use wheelchairs from having face-to-face interaction and using the counter surface to fill out forms, etc. in the way that the general public can. A higher counter surface was used to provide forms and brochures which are contained in baskets or holders that are not within accessible reach range.

People who visit the facility to make use of the programs, services and activities are screened in the lobby, and may continue to an office where staff can provide further services. Offices lacked tactile signage where visual signs were provided. Some offices lacked accessible door hardware and the vision lights (windows) at some offices were not installed with a lower edge below 43" high to allow short people, or people who use wheelchairs, to view the interior spaces. Maneuvering clearance in some offices was not accessible for people who use mobility assist devices. The facility was identified with two single accommodation toilet rooms and neither of the toilet rooms were accessible to people using wheelchairs. The square footage of the toilet rooms was not adequate to provide required maneuvering clearance at the entrance door or within the toilet room. Also, no separate men and women's toilet rooms were provided for staff, as required by California Labor Code §2350. One meeting room was identified in the facility and the entry door lacked required maneuvering clearance and the group tables in the center of the space were not identified as accessible. An additional accessible table is required in that common use area.

The following barrier data records provide more detailed information on the barriers described above.





Field Date:	6/30/2017 Report Date: 7/19/2017 Barrier #: 1
Facility:	Public Health (MCAH) - 317 2nd St, Eureka
Location:	Exterior - Walkway to Building Entrance from 2nd St
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decre	ee: No Paragraph: M.51 Dwg: N/A
Barrier Area:	Accessible Route - Exterior Remediation: Required
Barrier Type:	Change in Level - 1/4" to 1/2"
Barrier Description:	Change in level greater than 1/4" in accessible route with no bevel
Code Referen	CBC 11B-403.4 and 2010 ADAS 403.4
As Built Description:	1/2" lip identified without a bevel in path of travel from sidewalk on 2nd Street
Proposed Solution:	Grind or repair to remove trip hazard
As-Built Meas	Quantity: LF Cost Estimate: \$1,500.00 BSR: 1 Necessary
X Coordinate:	-124.168301979079 Y Coordinate: 40.8043190091848 Z Coordinate: 15.207464
Implementation	on: Priority 1 Phase Date Status Open
Notes:	OWNER
Field Date:	6/30/2017 Report Date: 7/19/2017 Barrier #: 2
Field Date: Facility:	6/30/2017 Report Date: 7/19/2017 Barrier #: 2 Public Health (MCAH) - 317 2nd St, Eureka
Facility:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St
Facility: Location:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St nsible: Karen Clower, ADA Coordinator
Facility: Location: Official Respo Consent Decre	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St nsible: Karen Clower, ADA Coordinator
Facility: Location: Official Respo Consent Decre Barrier Area:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A
Facility: Location: Official Respo Consent Decre Barrier Area:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Accessible Route - Exterior Remediation: Required
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St Insible: Karen Clower, ADA Coordinator Insible: No Paragraph: M.51 Dwg: N/A Accessible Route - Exterior Remediation: Required Turning Space - 360 Degree Turn (<60")
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St Insible: Karen Clower, ADA Coordinator Insible: No Paragraph: M.51 Dwg: N/A Accessible Route - Exterior Remediation: Required Turning Space - 360 Degree Turn (<60") Circular turning space not minimum of 60" in diameter (including toe/knee space)
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St Insible: Karen Clower, ADA Coordinator Insible: No Paragraph: M.51 Dwg: N/A Accessible Route - Exterior Remediation: Required Turning Space - 360 Degree Turn (<60") Circular turning space not minimum of 60" in diameter (including toe/knee space) Ces: CBC 11B-304.3.1 and 2010 ADAS 304.3.1
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Accessible Route - Exterior Remediation: Required Turning Space - 360 Degree Turn (<60") Circular turning space not minimum of 60" in diameter (including toe/knee space) ces: CBC 11B-304.3.1 and 2010 ADAS 304.3.1 60" turning space not provided at change of direction in path to building entrance Alter floor or ground surface to comply E25 Quantity: SF Cost Estimate: \$3,125.00 BSR: 2 Recommended
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Accessible Route - Exterior Remediation: Required Turning Space - 360 Degree Turn (<60") Circular turning space not minimum of 60" in diameter (including toe/knee space) ces: CBC 11B-304.3.1 and 2010 ADAS 304.3.1 60" turning space not provided at change of direction in path to building entrance Alter floor or ground surface to comply 125 Quantity: SF Cost Estimate: \$3,125.00 BSR: 2 Recommended
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Building Entrance from 2nd St Insible: Karen Clower, ADA Coordinator Insible: Karen Clower, ADA Coordinator Insible: Remediation: Required Accessible Route - Exterior Remediation: Required Turning Space - 360 Degree Turn (<60") Circular turning space not minimum of 60" in diameter (including toe/knee space) Ces: CBC 11B-304.3.1 and 2010 ADAS 304.3.1 60" turning space not provided at change of direction in path to building entrance Alter floor or ground surface to comply E25 Quantity: SF Cost Estimate: \$3,125.00 BSR: 2 Recommended -124.168303 Y Coordinate: 40.804412 Z Coordinate: 15.207464



Field Date:	6/30/2017 Report Date: 7/19/2017 Barrier #: 3A
Facility:	Public Health (MCAH) - 317 2nd St, Eureka
Location:	Exterior - Parking Lot - North of Building
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decr	ee: No Paragraph: M.51 Dwg: N/A
Barrier Area:	Parking Remediation: Required
Barrier Type:	Tow-Away Sign
Barrier Description:	No tow-away sign provided at lot entry or accessible stalls
Code Referen	ces: CBC 11B-502.8
As Built Description:	No sign provided
Proposed Solution:	Provide compliant sign
As-Built Meas	Quantity: EACH Cost Estimate: \$250.00 BSR: 2 Recommended
X Coordinate:	-124.168360987678 Y Coordinate: 40.8046309836208 Z Coordinate: 14.551235
Implementati	on: Priority 1 Phase Date Status Open
	OJ identified barriers in this City of Eureka parking lot, which is used by Public Health MCAH at 2nd Street.
Field Date:	6/30/2017 Report Date: 7/19/2017 Barrier #: 3B
Facility:	Public Health (MCAH) - 317 2nd St, Eureka
Location:	Exterior - Parking Lot - North of Building
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decr	ee: Yes Paragraph: J.2.a.i DOJ# 1 Dwg: N/A
Barrier Area:	Parking Remediation: Required
Barrier Type:	Location - Dispersion
Barrier Description:	Accessible route not provided to dispersed stalls at various building locations
Code Referen	ces: CBC 11B-208.3.1 and 2010 ADAS 208.3.1
As Built Description:	Accessible stalls not provided on shortest possible route to each accessible building entry
Proposed	
Solution:	Relocate 1 accessible stall on shortest possible route to building entrance
As-Built Meas	l
As-Built Meas	
As-Built Meas	1 Quantity: EACH Cost Estimate: \$1,400.00 BSR: 2 Recommended 124.168360987678 Y Coordinate: 40.8046309836208 Z Coordinate: 14.551235



Field Date:	6/30/2017 Report Date: 7/19/2017 Barrier #: 3C
Facility:	Public Health (MCAH) - 317 2nd St, Eureka
Location:	Exterior - Parking Lot - North of Building
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decre	ee: No Paragraph: M.51 Dwg: N/A
Barrier Area:	Parking Remediation: Recommended
Barrier Type:	Marked Crossing
Barrier Description:	No marked crossing where accessible route crosses through vehicular traffic lane
Code Referen	CBC 11B-502.3 and 2010 ADAS Advisory 502.3
As Built Description:	No accessible route from walkway across the vehicular traffic lane
Proposed Solution:	Recommended: provide yellow marked crossing as safe route through parking lot or vehicular traffic lane
As-Built Meas	Quantity: LF Cost Estimate: \$495.00 BSR: 2 Recommended
X Coordinate:	-124.168360987678 Y Coordinate: 40.8046309836208 Z Coordinate: 14.551235
Implementation	on: Priority 1 Phase Date Status Open
	table warnings should be provided along transition from the walkway on opposite side of alley entering vehicular traffic lane. ALLEY OWNER
Field Date:	6/30/2017 Report Date: 7/19/2017 Barrier #: 3D
Facility:	Public Health (MCAH) - 317 2nd St, Eureka
Location:	Exterior - Parking Lot - North of Building
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decre	ee: No Paragraph: M.51 Dwg: N/A
Barrier Area:	Curb Ramp - Perpendicular Remediation: Required
Barrier Type:	Detectable Warnings - Truncated Dome Location
Barrier Description:	No truncated domes provided at curb ramp or existing truncated domes not within 6" - 8" of transition into roadway
Code Referen	ces: CBC 11B-705.1.2
As Built Description:	No detectable warnings provided at transition into vehicular traffic lane
Proposed Solution:	Provide compliant truncated domes
As-Built Meas	4 Quantity: EACH Cost Estimate: \$5,600.00 BSR: 2 Recommended
X Coordinate:	-124.168360987678 Y Coordinate: 40.8046309836208 Z Coordinate: 14.551235
Implementation	on: Priority 1 Phase Date Status Open
Notes:	CITY



Field Date:	6/30/2017 Report Date: 7/19/2017 Barrier #: 4A
Facility:	Public Health (MCAH) - 317 2nd St, Eureka
Location:	Exterior - Walkway to Entrance from Parking Lot
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decre	ee: No Paragraph: M.51 Dwg: N/A
Barrier Area:	Blended Transitions Remediation: Required
Barrier Type:	Detectable Warnings - Truncated Dome Location
Barrier Description:	No truncated domes provided at curb ramp or existing truncated domes not within 6" - 8" of transition into roadway
Code Referen	ces: PROWAG 208.1 and CBC 11B-705.1.2
As Built Description:	Crossing into vehicular traffic lane not identified for the visually impaired
Proposed Solution:	Provide compliant truncated domes
As-Built Meas	: 4 Quantity: LF Cost Estimate: \$1,400.00 BSR: 2 Recommended
X Coordinate:	-124.168341038748 Y Coordinate: 40.8045729808509 Z Coordinate: 10.232574
Implementati	on: Priority 1 Phase Date Status Open
Notes:	OWNER
Field Date:	6/30/2017 Report Date: 7/19/2017 Barrier #: 4B
Field Date: Facility:	6/30/2017 Report Date: 7/19/2017 Barrier #: 4B Public Health (MCAH) - 317 2nd St, Eureka
Facility: Location:	Public Health (MCAH) - 317 2nd St, Eureka
Facility: Location:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator
Facility: Location: Official Respo Consent Decre Barrier Area:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Blended Transitions Remediation: Required
Facility: Location: Official Respo Consent Decre Barrier Area:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A
Facility: Location: Official Respo Consent Decre Barrier Area:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Blended Transitions Remediation: Required
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Blended Transitions Remediation: Required Cross Slope - Existing (2.1% to 3.0%)
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Blended Transitions Remediation: Required Cross Slope - Existing (2.1% to 3.0%) Ramp run cross slope exceeds 2.0% (2.1% to 3.0%)
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Blended Transitions Remediation: Required Cross Slope - Existing (2.1% to 3.0%) Ramp run cross slope exceeds 2.0% (2.1% to 3.0%) ces: CBC 11B-406.5.7 and PROWAG R304.5.3
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Blended Transitions Remediation: Required Cross Slope - Existing (2.1% to 3.0%) Ramp run cross slope exceeds 2.0% (2.1% to 3.0%) ces: CBC 11B-406.5.7 and PROWAG R304.5.3 2.6% cross slope Demolish existing and construct new curb ramp
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Blended Transitions Remediation: Required Cross Slope - Existing (2.1% to 3.0%) Ramp run cross slope exceeds 2.0% (2.1% to 3.0%) ces: CBC 11B-406.5.7 and PROWAG R304.5.3 2.6% cross slope Demolish existing and construct new curb ramp
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Public Health (MCAH) - 317 2nd St, Eureka Exterior - Walkway to Entrance from Parking Lot nsible: Karen Clower, ADA Coordinator ee: No Paragraph: M.51 Dwg: N/A Blended Transitions Remediation: Required Cross Slope - Existing (2.1% to 3.0%) Ramp run cross slope exceeds 2.0% (2.1% to 3.0%) ces: CBC 11B-406.5.7 and PROWAG R304.5.3 2.6% cross slope Demolish existing and construct new curb ramp : 1 Quantity: EACH Cost Estimate: \$2,500.00 BSR: 4 Low Severity -124.168341038748 Y Coordinate: 40.8045729808509 Z Coordinate: 10.232574



ield Date: 6/30/2017 Report Date: 7/19/2017 Barrier #: 4C	
acility: Public Health (MCAH) - 317 2nd St, Eureka	
ocation: Exterior - Walkway to Entrance from Parking Lot	
Official Responsible: Karen Clower, ADA Coordinator	
Consent Decree: No Paragraph: M.51 Dwg: N/A	
Barrier Area: Blended Transitions Remediation: Required	
Sarrier Type: Counter Slope - Existing (6.6% to 8.2%)	
Gutter slope exceeds 5.0% (6.6% to 8.2%) Description:	
Code References: CBC 11B-406.5.8 and PROWAG R304.5.4	
As Built 7.0% gutter slope Description:	
Proposed Demolish existing and construct new gutter colution:	
As-Built Meas: 3 Quantity: SF Cost Estimate: \$375.00 BSR: 2 Recommended	
Coordinate: -124.168341038748 Y Coordinate: 40.8045729808509 Z Coordinate: 10.232574	
mplementation: Priority 1 Phase Date Status Open	
Notes: OWNER	
ield Date: 6/30/2017 Report Date: 7/19/2017 Barrier #: 5	
ield Date: 6/30/2017 Report Date: 7/19/2017 Barrier #: 5 acility: Public Health (MCAH) - 317 2nd St, Eureka	
Public Health (MCAH) - 317 2nd St, Eureka	
acility: Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot	
Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Sidewalks Remediation: Required	
Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A	Mar
Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Sidewalks Remediation: Required	
Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Sidewalks Remediation: Required Barrier Type: Cross Slope - Existing (5.0% or more) Barrier Cross slope exceeds 2.0% (5.0% or more)	
Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Sidewalks Remediation: Required Barrier Type: Cross Slope - Existing (5.0% or more) Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Type: Cross Slope - Existing (5.0% or more)	
Public Health (MCAH) - 317 2nd St, Eureka cocation: Exterior - Walkway to Entrance from Parking Lot Difficial Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Sidewalks Remediation: Required Barrier Type: Cross Slope - Existing (5.0% or more) Code References: CBC 11B-403.3 and PROWAG 302.6 Sas Built 5.5% cross slope	
Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Sidewalks Remediation: Required Barrier Type: Cross Slope - Existing (5.0% or more) Code References: CBC 11B-403.3 and PROWAG 302.6 As Built Description: Croposed Demolish existing and construct new route	
Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Sidewalks Barrier Type: Cross Slope - Existing (5.0% or more) Code References: CBC 11B-403.3 and PROWAG 302.6 As Built Description: Demolish existing and construct new route Proposed Proposed Column (Column (C	
Public Health (MCAH) - 317 2nd St, Eureka ocation: Exterior - Walkway to Entrance from Parking Lot Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: N/A Barrier Area: Sidewalks Barrier Type: Cross Slope - Existing (5.0% or more) Code References: CBC 11B-403.3 and PROWAG 302.6 As Built Description: Proposed Colution: Proposed Colution: Proposed Colution: Sa-Built Meas: 32 Quantity: LF Cost Estimate: \$4,000.00 BSR: 1 Necessary	



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 6A	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Entrance		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	S. Annual Control
Barrier Area:	Signage	Remediation: Required	
Barrier Type:	ISA - Accessible Entry		
Barrier Description:	No sign identifying do	or as accessible	
Code Referen	ces: CBC 11B-216.6 ar	nd 2010 ADAS 216.6	
As Built Description:	Accessible entrance ha	as no ISA sign	
Proposed Solution:	Provide ISA at accessib	ole entrance door	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 BSR	1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coordi	nate: N/A
Implementati	on: Priority 4	Phase Date	Status Open
Notes:		OW	NER
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 6B	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Entrance		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
		Paragraph: M.51 Dwg: 1 of 1	7
Consent Decre	ee: No	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CONTRACTOR OF THE PERSON OF TH
Consent Decre Barrier Area:		Remediation: Required	The state of the s
Barrier Area:		Remediation: Required	
Barrier Area:	Signage Room ID Sign - No Tac	Remediation: Required	ually impaired
Barrier Area: Barrier Type: Barrier Description:	Signage Room ID Sign - No Tac	Remediation: Required tile Information d for sighted people lacks tactile info for the visu	ually impaired
Barrier Area: Barrier Type: Barrier Description:	Signage Room ID Sign - No Tac Room ID sign provided ces: CBC 11B-216.2 ar	Remediation: Required tile Information d for sighted people lacks tactile info for the visu	ually impaired
Barrier Area: Barrier Type: Barrier Description: Code Referen	Room ID Sign - No Tac Room ID Sign provided Room ID sign provided ces: CBC 11B-216.2 ar No tactile information	Remediation: Required stile Information d for sighted people lacks tactile info for the visual and 2010 ADAS 216.2	
Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed	Signage Room ID Sign - No Tac Room ID sign provided ces: CBC 11B-216.2 ar No tactile information Provide room ID sign v	Remediation: Required stile Information d for sighted people lacks tactile info for the visual 2010 ADAS 216.2 provided where visual sign exists with tactile information at wall at latch side of deciding the side of dec	
Barrier Area: Barrier Type: Barrier Description: Code Referent As Built Description: Proposed Solution:	Room ID Sign - No Tac Room ID Sign provided ces: CBC 11B-216.2 ar No tactile information Provide room ID sign v : 1 Quantity:	Remediation: Required Itile Information In for sighted people lacks tactile info for the visual and 2010 ADAS 216.2 In provided where visual sign exists With tactile information at wall at latch side of description of the visual sign exists EACH Cost Estimate: \$250.00 BSR	oor
Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Room ID Sign - No Tac Room ID Sign provided ces: CBC 11B-216.2 ar No tactile information Provide room ID sign v 1 Quantity: N/A	Remediation: Required Itile Information In for sighted people lacks tactile info for the visual and 2010 ADAS 216.2 In provided where visual sign exists With tactile information at wall at latch side of description of the visual sign exists EACH Cost Estimate: \$250.00 BSR	oor :: 1 Necessary



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 6C
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Location: Entrance
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: Required
Barrier Type: Door/Gate Landing - Slope 4.1% to 5.0%
Barrier Door/Gate landing is not level on both sides of door (4.1% to 5.0%) Description:
Code References: CBC 11B-404.2.4.4 and 2010 ADAS 404.2.4.4
As Built 5.0% running slope Description:
Proposed Solution: Demolish and reconstruct level landing. Slope too severe to remediate with automatic door opening device
As-Built Meas: 40 Quantity: SF Cost Estimate: \$5,000.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 1 Phase Date Status Open
Notes: OWNER
Field Date: 6/29/2017 Report Date: 9/30/2019 Barrier #: 6D
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Location: Entrance
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: N/A
Barrier Type: Doormats
Barrier Type: Doormats Barrier Doormat not anchored to floor (trip hazard)
Barrier Type: Doormats Barrier Doormat not anchored to floor (trip hazard) Description:
Barrier Type: Doormats Barrier Doormat not anchored to floor (trip hazard) Code References: CBC 11B-302.2 and 2010 ADAS 302.2 As Built Existing door mat not recessed or secured
Barrier Type: Doormats Barrier Doormat not anchored to floor (trip hazard) Code References: CBC 11B-302.2 and 2010 ADAS 302.2 As Built Description: Proposed Secure mat to floor. When mat provides equivalent facilitation on a non-slip resistant floor, the
Barrier Type: Doormats Barrier Doormat not anchored to floor (trip hazard) Code References: CBC 11B-302.2 and 2010 ADAS 302.2 As Built Existing door mat not recessed or secured Description: Proposed Secure mat to floor. When mat provides equivalent facilitation on a non-slip resistant floor, the mat may stay in place when maintained
Barrier Type: Doormats Barrier Doormat not anchored to floor (trip hazard) Code References: CBC 11B-302.2 and 2010 ADAS 302.2 As Built Description: Proposed Secure mat to floor. When mat provides equivalent facilitation on a non-slip resistant floor, the mat may stay in place when maintained As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 1 Necessary



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 6E	
Facility: Public Health (MCAH) - 317 2nd St, Eureka	
Location: Entrance	h
Official Responsible: Karen Clower, ADA Coordinator	
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Signage Remediation: Required	
Barrier Type: Tactile Exit Sign - Exit	
Barrier Ground floor doors that exit to exterior not provided with signs stating "EXIT" Description:	
Code References: CBC 11B-216.4.1 & 11B-703 and 2010 ADAS 216.4.1	
As Built No tactile sign provided where required Description:	
Proposed Provide compliant sign at exit side of door Solution:	
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary	
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
Implementation: Priority 4 Phase Date Status Open	
Notes: OWNER	
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 7A	1
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 7A Public Health (MCAH) - 317 2nd St, Eureka	H
17,20,202	
Public Health (MCAH) - 317 2nd St, Eureka	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required	
Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Flyer holder point of control not at max. 48" high reach	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description:	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description: Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1 As Built Flyers not located within accessible reach range	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description: Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1 As Built Flyers not located within accessible reach range Proposed Move to provide accessible reach range or provide assistance	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description: Flyer holder point of control not at max. 48" high reach Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1 As Built Flyers not located within accessible reach range Proposed Solution: Move to provide accessible reach range or provide assistance	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description: Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1 As Built Plyers not located within accessible reach range Proposed Solution: Proposed Move to provide accessible reach range or provide assistance As-Built Meas: 1 Quantity: JOB Cost Estimate: \$0.00 BSR: 3 Hindrance	



Facility: Public Health (MCAH) - 317 2nd St, Eureka			
Location: Lobby			
Official Responsible: Karen Clower, ADA Coordinator			
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1			
Barrier Area: Controls and Mechanisms Remediation: Required			
Barrier Type: Electrical Outlets - Side Reach Low Unobstructed			
Barrier Description: Electrical outlet control box not min. 15" high measured to the bottom of the outlet box			
Code References: CBC 11B-308.1.2, 11B-308.3.1 and 2010 ADAS 308.3			
As Built Description: 13" to top of box in lobby where waiting area is provided			
Proposed Relocate outlet to area with min. 15" low reach or max. 48" high reach Solution:			
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$750.00 BSR: 3 Hindrance			
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A			
Implementation: Priority 2 Phase Date Status Open			
Notes: OWNER			
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 7C			
E. All			
Facility: Public Health (MCAH) - 317 2nd St, Eureka			
Location: Public Health (MCAH) - 317 2nd St, Eureka Lobby			
Location: Lobby			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: N/A			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: N/A Barrier Type: Operable Part - Side Reach High (Safe Harbor) Barrier Operable part at max. 54" high			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: N/A Barrier Type: Operable Part - Side Reach High (Safe Harbor) Barrier Description: Operable part at max. 54" high			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: N/A Barrier Type: Operable Part - Side Reach High (Safe Harbor) Barrier Operable part at max. 54" high Description: Code References: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i) As Built 51" high control at hand sanitizer			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: N/A Barrier Type: Operable Part - Side Reach High (Safe Harbor) Barrier Description: Operable part at max. 54" high Code References: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i) As Built Description: Proposed No remediation required. Control or mechanism complied with prior code and is granted safe			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: N/A Barrier Type: Operable Part - Side Reach High (Safe Harbor) Barrier Description: Code References: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i) As Built Description: Proposed No remediation required. Control or mechanism complied with prior code and is granted safe harbor			
Location: Lobby Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: N/A Barrier Type: Operable Part - Side Reach High (Safe Harbor) Barrier Description: Code References: ADA Title II, Subpart D, § 35.150 Existing facilities § 35.150(b)(2)(i) As Built Description: Proposed No remediation required. Control or mechanism complied with prior code and is granted safe Solution: As-Built Meas: 1 Quantity: EACH Cost Estimate: \$0.00 BSR: 3 Hindrance			



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 7D	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Lobby		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Counters and Tables	Remediation: Required	
Barrier Type:	Counter - Knee Cleara	nce	
Barrier Description:	Knee clearance of at le	east 27" high, 30" wide and 19" deep not pro	vided
Code Referen	ces: CBC 11B-306.3 ar	d 2010 ADAS 306.3	
As Built Description:	Multiple service count	ers have knee clearance 9-1/2" deep. Surfac	e height is compliant
Proposed Solution:	Remodel counters to p program provided	provide knee/toe clearance at min. 1 counter	or one of each type of
As-Built Meas	: 20 Quantity:	SF Cost Estimate: \$3,500.00	SSR: 2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A Z Coo	rdinate: N/A
Implementati	on: Priority 2	Phase Date	Status Open
Notes: Peop	le who use wheelchairs	cannot pull under the counter to face the st	aff and interact. OWNER
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 7E	1
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Lobby		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Controls and Mechani	sms Remediation: Required	
Barrier Type:	Operable Part - Side R	each High Unobstructed	
Barrier Description:	Operable part not at n	nin. 15" or max. 48" high	
Code Referen	ces: CBC 11B-308.3.1	and 2010 ADAS 308.3.1	
As Built Description:	50" high drop baskets	and brochures at 58" high	
Proposed Solution:	Relocate control or me	echanism to min. 15" or max. 48" high or pro	vide assistance
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$750.00	3 Hindrance
X Coordinate:	N/A	Y Coordinate: N/A Z Coo	rdinate: N/A
Implementation	on: Priority 2	Phase Date	Status Open
Notes:			COUNTY



Field Date:	6/29/2017 Repo	ort Date: 7/19/2017 B	arrier #: 8A	
Facility:	Public Health (MCAH) - 317 2nd St, Eureka			
Location:	Meeting Room 115			
Official Respo	nsible: Karen Clower	r, ADA Coordinator		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Signage	Remediatio	n: Required	
Barrier Type:	Room ID Sign - No Tac	tile Information		
Barrier Description:	Room ID sign provided	d for sighted people lacks ta	ctile info for the visuall	y impaired
Code Referen	ces: CBC 11B-216.2 ar	nd 2010 ADAS 216.2		
As Built Description:	No tactile information	provided where visual sign	exists	
Proposed Solution:	Provide room ID sign	with tactile information at w	vall at latch side of door	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$	250.00 BSR: 1	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinat	e: N/A
Implementati	on: Priority 4	Phase	Date	Status Open
Notes:				COUNTY
Field Date:	5/16/2018 Repo	ort Date: 9/30/2019 B	arrier #: 8B	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka		
Location:	Meeting Room 115			1 2 2 3 2 3
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: Yes	Paragraph: J.2.b.i DOJ#2	2 Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediatio	on: N/A	
Barrier Type:	Door/Gate Hardware	- Operation		
Barrier Description:	Hardware not operab	le with a closed fist		
Code Referen	ces: CBC 11B-404.2.7	and 2010 ADAS 404.2.7		
As Built Description:	Lever hardware has be	een installed on door		
Proposed Solution:	Barrier removed			
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$	0.00 BSR: 1	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinat	e: N/A
Implementati	on: Priority 2	Phase	Date	Status Closed
Notes:				



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 8C			
Facility: Public Health (MCAH) - 317 2nd St, Eureka			
Location: Meeting Room 115			
Official Responsible: Karen Clower, ADA Coordinator			
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1			
Barrier Area: Clear Floor Space Remediation: Required			
Barrier Type: Clear Floor Space - Wheelchair Use (Office)			
Barrier Clear floor space of min. 30" by 48" not provided in location where programs, services or activities are provided			
Code References: CBC 11B-305 and 2010 ADAS 203.9 & 305			
As Built Clear floor space for individuals with disabilities not provided Description:			
Proposed Move stored items or alter space so individuals with disabilities can approach, enter and exit space			
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$0.00 BSR: 1 Necessary			
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A			
Implementation: Priority 2 Phase Date Status Open			
Notes: COUNTY			
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 8D			
Facility: Public Health (MCAH) - 317 2nd St, Eureka			
Location: Meeting Room 115			
Official Responsible: Karen Clower, ADA Coordinator			
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1			
Barrier Area: Controls and Mechanisms Remediation: Required			
Barrier Type: Flyer Holder - High Reach Range			
Barrier Flyer holder point of control not at max. 48" high reach Description:			
Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1			
As Built Flyers not located within accessible reach range Description:			
Proposed Move to provide accessible reach range or provide assistance Solution:			
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$0.00 BSR: 3 Hindrance			
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A			
Implementation: Priority 2 Phase Date Status Open			
Notes: COUNTY			



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 9A		
Facility:	Public Health (MCAH) - 317 2nd St, Eureka			
Location:	Meeting Room 114			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1		
Barrier Area:	Signage	Remediation: Required		
Barrier Type:	Room ID Sign - No Tac	tile Information		
Barrier Description:	Room ID sign provided	I for sighted people lacks tactile info for the v	risually impaired	
Code Referen	ces: CBC 11B-216.2 ar	d 2010 ADAS 216.2		
As Built Description:	No tactile information	provided where visual sign exists		
Proposed Solution:	Provide room ID sign v	vith tactile information at wall at latch side o	f door	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00	SR: 1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A Z Coo	rdinate: N/A	
Implementati	on: Priority 4	Phase Date	Status Open	
Notes:			COUNTY	
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 9B		
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	y y	
Location:	Meeting Room 114			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	(1)	
Barrier Area:	Accessible Route - Inte	erior Remediation: Required		
Barrier Type:	Turning Space - 360 D	egree Turn (<60" - Stored Items)		
Barrier Description: Circular turning space not minimum of 60" in diameter (including toe/knee space)				
Code Referen	ces: CBC 11B-304.3.1	and 2010 ADAS 304.3.1		
As Built 52-1/2" turning space in path between desks, and 47" clear floor space between second desk and wall				
•		,	sade between second desk	
Proposed Solution:	and wall	provide wheelchair access	add dem cen dedding dedic	
•	and wall Rearrange furniture to	provide wheelchair access	SSR: 1 Necessary	
Solution:	Rearrange furniture to	provide wheelchair access JOB Cost Estimate: \$0.00		
Solution: As-Built Meas	Rearrange furniture to 1 Quantity: N/A	provide wheelchair access JOB Cost Estimate: \$0.00	SSR: 1 Necessary	



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 9C		
Facility:	Public Health (MCAH) - 317 2nd St, Eureka			
Location:	Meeting Room 114			
Official Responsible: Karen Clower, ADA Coordinator				
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1		
Barrier Area:	Controls and Mechanis	Remediation: Required		
Barrier Type:	Flyer Holder - High Rea	nch Range		
Barrier Description:	Flyer holder point of co	ontrol not at max. 48" high reach		
Code Referen	ces: CBC 11B-308.2.1	and 2010 ADAS 308.2.1		
As Built Description:	Flyers not located with	in accessible reach range		
Proposed Solution:	Move to provide acces	sible reach range or provide assistance		
As-Built Meas	: 1 Quantity:	JOB Cost Estimate: \$0.00 BSR	3 Hindrance	
X Coordinate:	N/A	Y Coordinate: N/A Z Coordi	nate: N/A	
Implementati	on: Priority 2	Phase Date	Status Open	
Notes:			COUNTY	
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 10A		
Facility:	Public Health (MCAH) - 317 2nd St, Eureka			
Location:	Meeting Room 113			
Official Respo	nsible: Karen Clower	ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1		
Barrier Area:	Signage	Remediation: Required		
Barrier Type:	Room ID Sign - No Tac	ile Information		
Barrier Description:	Room ID sign provided	for sighted people lacks tactile info for the visu	ually impaired	
Code Referen	ces: CBC 11B-216.2 an	d 2010 ADAS 216.2		
As Built Description:	No tactile information	provided where visual sign exists		
Proposed Solution:	Provide room ID sign v	vith tactile information at wall at latch side of d	oor	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 BSR	1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A Z Coordi	nate: N/A	
Implementati	on: Priority 4	Phase Date	Status Open	
Notes:			COUNTY	



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017	Barrier #: 10B	
Facility:	Public Health (MCAH) - 317 2nd St, Eureka			
Location:	Meeting Room 113			
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Controls and Mechanis	sms Remediati	ion: Required	
Barrier Type:	Operable Part - Side R	each High Unobstructed		
Barrier Description:	Operable part not at n	nin. 15" or max. 48" high		
Code Referen	ces: CBC 11B-308.3.1	and 2010 ADAS 308.3.1		
As Built Description:	55" high hand sanitize	r dispenser adjacent to en	try door	
Proposed Solution:	Relocate control or me	echanism to min. 15" or m	ax. 48" high	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$750.00 BSR: 3	Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinat	e: N/A
Implementati	on: Priority 2	Phase	Date	Status Open
Notes:				COUNTY
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017	Barrier #: 10C	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	ž.	
Location:	Meeting Room 113		•	
Official Respo	nsible: Karen Clower	, ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Accessible Route - Inte	erior Remediati	on: Required	
Barrier Type:	Turning Space - 360 De	egree Turn (<60" - Stored I	tems)	
Barrier Description:	Circular turning space	not minimum of 60" in dia	meter (including toe/kno	ee space)
Code Referen	ces: CBC 11B-304.3.1	and 2010 ADAS 304.3.1		
As Built Description:	52" turning space betw	veen desk and wall		
Proposed Solution:	Rearrange furniture to	provide wheelchair acces	S	
As-Built Meas	: 1 Quantity:	JOB Cost Estimate:	\$0.00 BSR: 1	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinat	e: N/A
Implementati	on: Priority 2	Phase	Date	Status Open
Notes:				COUNTY



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 10D
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Location: Meeting Room 113
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Controls and Mechanisms Remediation: Required
Barrier Type: Flyer Holder - High Reach Range
Barrier Flyer holder point of control not at max. 48" high reach Description:
Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1
As Built Flyers not located within accessible reach range Description:
Proposed Move to provide accessible reach range or provide assistance Solution:
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$0.00 BSR: 3 Hindrance
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes: COUNTY
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 11A
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Location: Meeting Room 112
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Signage Remediation: Required
Barrier Type: Room ID Sign - No Tactile Information
Barrier Room ID sign provided for sighted people lacks tactile info for the visually impaired Description:
Description:
Description: Code References: CBC 11B-216.2 and 2010 ADAS 216.2 As Built No tactile information provided where visual sign exists
Description: Code References: CBC 11B-216.2 and 2010 ADAS 216.2 As Built No tactile information provided where visual sign exists Description: Proposed Provide room ID sign with tactile information at wall at latch side of door
Description: Code References: CBC 11B-216.2 and 2010 ADAS 216.2 As Built Description: Proposed Solution: Provide room ID sign with tactile information at wall at latch side of door
Description: Code References: CBC 11B-216.2 and 2010 ADAS 216.2 As Built Description: Proposed Solution: As-Built Meas: 1 Quantity: EACH Cost Estimate: \$250.00 BSR: 1 Necessary



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 1	L1B
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Meeting Room 112		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1	of 1
Barrier Area:	Doors or Gates	Remediation: Require	ed
Barrier Type:	Maneuvering Cl - Int F	ront App/Pull 18"	
Barrier Description:	Door/Gate at pull side	lacks min. 18" beyond latch side of do	or
Code Referen	ces: CBC Figure 11B-4	04.2.4.1 and 2010 ADAS 404.2.4.1	
As Built Description:	8" strike edge clearan	ce at exit side of door between desk an	d door frame
Proposed Solution:	Rearrange furniture to	provide wheelchair access, as needed	
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$0.00	BSR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate: N/A
Implementati	on: Priority 2	Phase Date	Status Open
Notes:			COUNTY
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 1	I1C
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	la Paris
Location:	Meeting Room 112		88
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1	of 1
Barrier Area:	Accessible Route - Inte	erior Remediation: Require	ed
Barrier Type:	Turning Space - 360 De	egree Turn (<60" - Stored Items)	
Barrier Description:	Circular turning space	not minimum of 60" in diameter (inclu	ding toe/knee space)
Code Referen	ces: CBC 11B-304.3.1	and 2010 ADAS 304.3.1	
As Built Description:	54-1/2" turning space	between desk and wall	
Proposed Solution:	Rearrange furniture to	provide wheelchair access	
As-Built Meas	: 1 Quantity:	JOB Cost Estimate: \$0.00	BSR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate: N/A
Implementati	on: Priority 2	Phase Date	Status Open
Notes:			COUNTY



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 12A	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Corridor 100B		
Official Respo	nsible: Karen Clower	ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of	1
Barrier Area:	Doors or Gates	Remediation: Required	The same of the sa
Barrier Type:	Vision Lights - Existing		
Barrier Description:	Doors, gates, and side	lights adjacent to opening not max. 43" a	bove floor/ground
Code Referen	ces: CBC 11B-404.2.11	and 2010 ADAS 404.2.11	
As Built Description:	Vision lights at 3 office	s lack a bottom edge at max. 43" high	
Proposed Solution:	Replace door or vision	panel in door	
As-Built Meas	Quantity:	EACH Cost Estimate: \$6,750.00	BSR: 3 Hindrance
X Coordinate:	N/A	Y Coordinate: N/A Z C	oordinate: N/A
Implementation	on: Priority 2	Phase Date	Status Open
Notes:			OWNER
Field Date:	5/16/2018 Repo	rt Date: 9/30/2019 Barrier #: 12B	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Corridor 100B		
Official Respo	nsible: Karen Clower	, ADA Coordinator	The second second
Consent Decre	ee: Yes	Paragraph: J.2.b.i DOJ# 2 Dwg: 1 of	1
Barrier Area:	Doors or Gates	Remediation: N/A	
Barrier Type:	Door/Gate Hardware -	Operation	
Barrier Description:	Hardware not operable	e with a closed fist	
Code Referen	ces: CBC 11B-404.2.7 a	and 2010 ADAS 404.2.7	
As Built Description:	Lever hardware has be	en installed on all doors at room 101A, 10	01B and 111
Proposed Solution:	Barriers removed		
As-Built Meas	Quantity:	EACH Cost Estimate: \$0.00	BSR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z C	oordinate: N/A
Implementation	on: Priority 2	Phase Date	Status Closed
Notes:			



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 13	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Meeting Room 107		
Official Respo	nsible: Karen Clower	, ADA Coordinator	(a) Table
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Signage	Remediation: Required	
Barrier Type:	Room ID Sign - No Tac	tile Information	
Barrier Description:	Room ID sign provided	for sighted people lacks tactile info for the vis	sually impaired
Code Referen	ces: CBC 11B-216.2 ar	d 2010 ADAS 216.2	
As Built Description:	No tactile information	provided where visual sign exists	
Proposed Solution:	Provide room ID sign v	vith tactile information at wall at latch side of	door
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 BS	R: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coord	dinate: N/A
Implementati	on: Priority 4	Phase Date	Status Open
Notes:			COUNTY
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 14A	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Meeting Room 108		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Signage	Remediation: Required	
Barrier Type:	Room ID Sign - No Tac	tile Information	
Barrier Description:	Room ID sign provided	for sighted people lacks tactile info for the vis	sually impaired
Code Referen	ces: CBC 11B-216.2 ar	d 2010 ADAS 216.2	
As Built Description:	No tactile information	provided where visual sign exists	
Proposed Solution:	Provide room ID sign v	vith tactile information at wall at latch side of	door
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 BS	R: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coord	dinate: N/A
Implementati	on: Priority 4	Phase Date	Status Open
Notes:			COUNTY



Field Date:	6/29/2017 Repor	t Date: 7/19/2017	Barrier #: 14B	
Facility:	Public Health (MCAH) -	317 2nd St, Eureka	16	
Location:	Meeting Room 108			M-Wa
Official Respo	nsible: Karen Clower,	ADA Coordinator		
Consent Decr	ee: No	Paragraph: M.51	Dwg: 1 of 1	2 (1)
Barrier Area:	Accessible Route - Inte	rior Remediati	ion: Required	
Barrier Type:	Turning Space - 360 De	gree Turn (<60" - Stored I	tems)	
Barrier Description:	Circular turning space I	not minimum of 60" in dia	meter (including toe/knee	e space)
Code Referen	ces: CBC 11B-304.3.1 a	ind 2010 ADAS 304.3.1		
As Built Description:	54-1/2" turning space I	petween desk and wall		
Proposed Solution:	Rearrange furniture to	provide wheelchair acces	S	
As-Built Meas	: 1 Quantity:	JOB Cost Estimate:	\$175.00 BSR: 11	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	: N/A
Implementati	on: Priority 2	Phase	Date	Status Open
Notes:				COUNTY
Field Date:	5/16/2018 Repor	t Date: 9/30/2019	Barrier #: 15A	
Facility:	Public Health (MCAH) -	317 2nd St, Eureka	- m	A
Location:	Unisex Restroom 1			††6.
Official Respo	nsible: Karen Clower,	ADA Coordinator	4	7
Consent Decre	ee: Yes	Paragraph: J.2.c.i DOJ#	3 Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediati	ion: N/A	
Barrier Type:	Sign - Braille/tactile Inf	ormation		
Barrier Description:	No sign with Braille/Ta	ctile information provided	I to identify restroom	
Code Referen	ces: CBC 11B-216.2 an	d 2010 ADAS 216.2		
As Built Description:	Compliant tactile sign բ	provided		
Proposed Solution:	Barrier removed			
As-Built Meas	: 0 Quantity:	EACH Cost Estimate:	\$0.00 BSR: 11	Necessary
X Coordinate:	N/A	Y Coordinate: N/A	Z Coordinate	: N/A
Implementati	on: Priority 3	Phase	Date	Status Closed
Notes: New	toilet room moved to lo	cation with adequate spa	ce	



Field Date:	6/29/2017 Repor	rt Date: 7/19/2017 Barrier #: 15B	
Facility:	Public Health (MCAH) -	- 317 2nd St, Eureka	a tta
Location:	Unisex Restroom 1		#ISSERM
Official Respo	nsible: Karen Clower,	, ADA Coordinator	To To
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	10
Barrier Area:	Restrooms	Remediation: N/A	
Barrier Type:	Sign - 12" Circle/triang	le with Braille	
Barrier Description:	12" geometric door sig	gn incorrectly has raised text or Braille on door sign	n
Code Referen	ces: CBC 11B-703.7.2.6	6	
As Built Description:	New door sign does no	ot contain Braille or tactile characters	
Proposed Solution:	Barrier removed		
As-Built Meas	Quantity:	EACH Cost Estimate: \$0.00 BSR:	1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coordina	te: N/A
Implementation	on: Priority 3	Phase Date	Status Closed
Notes:			
Field Date:	5/16/2018 Repor	rt Date: 9/30/2019 Barrier #: 15C	
Field Date: Facility:	5/16/2018 Repor		A tto
			∆
Facility: Location:	Public Health (MCAH) -	- 317 2nd St, Eureka	≜
Facility: Location:	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower,	- 317 2nd St, Eureka	△
Facility: Location: Official Respo Consent Decre Barrier Area:	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower, ee: Yes Doors or Gates	ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A	A His
Facility: Location: Official Respo Consent Decre Barrier Area:	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower,	ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A	A His
Facility: Location: Official Respo Consent Decre Barrier Area:	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower, ee: Yes Doors or Gates Maneuvering Cl - Int Fr	ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A	A PHS
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower, ee: Yes Doors or Gates Maneuvering CI - Int Fr	- 317 2nd St, Eureka , ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A ront App/Pull 18"	
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description:	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower, ee: Yes Doors or Gates Maneuvering CI - Int Fr Door/Gate at pull side ces: CBC Figure 11B-40	ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A ront App/Pull 18" lacks min. 18" beyond latch side of door 04.2.4.1 and 2010 ADAS 404.2.4.1 to provide wheelchair access. Compliant clear floo	
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower, ee: Yes Doors or Gates Maneuvering Cl - Int Fr Door/Gate at pull side Ces: CBC Figure 11B-40 Toilet room enlarged t	ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A ront App/Pull 18" lacks min. 18" beyond latch side of door 04.2.4.1 and 2010 ADAS 404.2.4.1 to provide wheelchair access. Compliant clear floo	
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower, ee: Yes Doors or Gates Maneuvering Cl - Int Fr Door/Gate at pull side ces: CBC Figure 11B-40 Toilet room enlarged t latch side in the pull di Barrier removed	ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A ront App/Pull 18" lacks min. 18" beyond latch side of door 04.2.4.1 and 2010 ADAS 404.2.4.1 to provide wheelchair access. Compliant clear floorection.	
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution:	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower, ee: Yes Doors or Gates Maneuvering Cl - Int Fr Door/Gate at pull side ces: CBC Figure 11B-40 Toilet room enlarged t latch side in the pull di Barrier removed : Quantity:	ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A ront App/Pull 18" lacks min. 18" beyond latch side of door 04.2.4.1 and 2010 ADAS 404.2.4.1 to provide wheelchair access. Compliant clear floorection.	r space provided on the
Facility: Location: Official Respo Consent Decre Barrier Area: Barrier Type: Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	Public Health (MCAH) - Unisex Restroom 1 nsible: Karen Clower, ee: Yes Doors or Gates Maneuvering CI - Int Fr Door/Gate at pull side ces: CBC Figure 11B-40 Toilet room enlarged t latch side in the pull di Barrier removed : 0 Quantity: N/A	ADA Coordinator Paragraph: J.2.c.ii DOJ# 4 Dwg: 1 of 1 Remediation: N/A ront App/Pull 18" lacks min. 18" beyond latch side of door 04.2.4.1 and 2010 ADAS 404.2.4.1 to provide wheelchair access. Compliant clear floorection. EACH Cost Estimate: \$0.00 BSR: 2	r space provided on the



Field Date: 5/16/2018 Report Date: 9/30/2019 Barrier #: 15D
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Location: Unisex Restroom 1
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Doors or Gates Remediation: N/A
Barrier Type: Maneuvering Cl - Stored Items
Barrier Door/Gate lacks required maneuvering clearance Description:
Code References: CBC Figure 11B-404.2.4.1 and 2010 ADAS 404.2.4.1
As Built Trash bin removed from strike edge clearance at exit side of door Description:
Proposed Barrier removed Solution:
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Closed
Notes:
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 15E
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 15E Facility: Public Health (MCAH) - 317 2nd St, Eureka
1929252
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Dispensers - Protruding Object Dispenser creates protruding object in path of travel
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Dispensers - Protruding Object Dispenser creates protruding object in path of travel Description:
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Dispensers - Protruding Object Barrier Description: Code References: CBC 11B-307.2 and 2010 ADAS 307.2 As Built New dispenser protrudes into the path of travel
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Dispensers - Protruding Object Barrier Description: Code References: CBC 11B-307.2 and 2010 ADAS 307.2 As Built Description: Proposed Relocate dispenser
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Dispensers - Protruding Object Barrier Description: Code References: CBC 11B-307.2 and 2010 ADAS 307.2 As Built Description: Proposed Solution: Relocate dispenser
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Dispensers - Protruding Object Barrier Description: Code References: CBC 11B-307.2 and 2010 ADAS 307.2 As Built Description: Proposed Relocate dispenser Solution: As-Built Meas: 1 Quantity: JOB Cost Estimate: \$125.00 BSR: 1 Necessary



Field Date: 5/16/2018 Report Date: 9/30/2019 Barrier #: 15F				
acility: Public Health (MCAH) - 317 2nd St, Eureka				
Location: Unisex Restroom 1				
Official Responsible: Karen Clower, ADA Coordinator				
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1				
Barrier Area: Restrooms Remediation: N/A				
Barrier Type: Dispensers - Control Point				
Barrier Dispenser control point or operating mechanism not max. 40" AFF Description:				
Code References: CBC 11B-603.5				
As Built New dispensers mounted below 40" high Description:				
Proposed Barrier removed Solution:				
As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 2 Recommended				
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A				
Implementation: Priority 3 Phase Date Status Closed				
Notes:				
Field Date: 5/16/2018 Report Date: 9/30/2019 Barrier #: 15G				
Facility: Public Health (MCAH) - 317 2nd St, Eureka				
Location: Unisex Restroom 1				
Official Responsible: Karen Clower, ADA Coordinator				
Consent Decree: Yes Paragraph: J.2.c.iii DOJ# 5 Dwg: 1 of 1				
Barrier Area: Restrooms Remediation: N/A				
Barrier Type: Mirror - Bottom Edge				
Barrier Mirror at lavatory/countertop not max. 40" AFF at edge of reflecting surface Description:				
Code References: CBC 11B-603.3 and 2010 ADAS 603.3				
As Built New mirror has bottom edge of the reflecting surface at 39-1/2" Description:				
Description.				
Proposed Barrier removed Solution:				
Proposed Barrier removed				
Proposed Barrier removed Solution:				
Proposed Barrier removed Solution: As-Built Meas: 0 Quantity: EACH Cost Estimate: \$0.00 BSR: 3 Hindrance				



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 15H	-		
Public Health (MCAH) - 317 2nd St, Eureka	k		
ation: Unisex Restroom 1			
Official Responsible: Karen Clower, ADA Coordinator			
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1			
Barrier Area: Restrooms Remediation: Required			
Barrier Type: Lavatory - Clear Floor Space			
No clear floor space 30" x 48" at lavatory to allow forward approach Description:			
Code References: CBC 11B-606.2 and 2010 ADAS 606.2			
As Built Trash bin blocks clear floor space at lavatory and maneuvering clearance at door Description:			
Proposed Remove trash bin to location where clear floor space at all fixtures and door are not obstructed Solution:	d		
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$450.00 BSR: 1 Necessary			
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A			
mplementation: Priority 3 Phase Date Status Open			
Notes: COUNTY			
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 15	7,6		
Facility: Public Health (MCAH) - 317 2nd St, Eureka			
1 1755/555			
Public Health (MCAH) - 317 2nd St, Eureka			
Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1			
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: N/A			
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1			
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: N/A			
Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: N/A Barrier Type: Lavatory - Centerline Barrier Lavatory adjacent to wall not min. 18" to the centerline of fixture			
Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: N/A Barrier Type: Lavatory - Centerline Barrier Description: Lavatory adjacent to wall not min. 18" to the centerline of fixture			
Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: N/A Barrier Type: Lavatory - Centerline Barrier Description: Code References: CBC 11B-606.6 As Built New lavatory centerline 18" OC from wall			
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: N/A Barrier Type: Lavatory - Centerline Barrier Description: Code References: CBC 11B-606.6 As Built Description: Proposed Barrier removed			
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: N/A Barrier Type: Lavatory - Centerline Barrier Coescription: Lavatory adjacent to wall not min. 18" to the centerline of fixture Code References: CBC 11B-606.6 As Built Description: Rew lavatory centerline 18" OC from wall Proposed Solution: Barrier removed			
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 1 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: N/A Barrier Type: Lavatory - Centerline Barrier Description: Code References: CBC 11B-606.6 As Built Description: New lavatory centerline 18" OC from wall Proposed Barrier removed Solution: As-Built Meas: O Quantity: JOB Cost Estimate: \$0.00 BSR: 2 Recommended			



Field Date:	5/16/2018 Repor	t Date: 9/30/2019	Barrier #: 15J	
Facility:	Public Health (MCAH) -	317 2nd St, Eureka		
Location:	Unisex Restroom 1			
Official Respo	nsible: Karen Clower,	ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediat	ion: N/A	
Barrier Type:	Lavatory - Drain Pipes			
Barrier Description:	Hot water and drainpip	oes accessible under lavat	ory not insulated or o	covered
Code Referen	ces: CBC 11B-606.5 and	d 2010 ADAS 606.5		
As Built Description:	New insulation provide	ed to cover entire drain pi	pes	
Proposed Solution:	Barrier removed			
As-Built Meas	: 0 Quantity:	EACH Cost Estimate:	\$0.00 BSI	R: 2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A	Z Coord	inate: N/A
Implementati	on: Priority 3	Phase	Date	Status Closed
Notes:				
Field Date:	5/16/2018 Repor	t Date: 9/30/2019	Barrier #: 15K	
Facility:	Public Health (MCAH) -	317 2nd St, Eureka		
Location:	Unisex Restroom 1			
Official Respo	nsible: Karen Clower,	ADA Coordinator		
Consent Decre	ee: Yes	Paragraph: J.2.c.v DOJ	# 7 Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediat	ion: N/A	
Barrier Type:	WC - Stall with Lavator	У		
Barrier Description:	Clear space in front of	closet not min. 60" wide >	(56" deep	
Code Referen	ces: CBC 11B-604.3.1 a	nd 2010 ADAS 604.3.1		
As Built Description:	Toilet room enlarged to	o provide wheelchair acce	ess	
Proposed Solution:	Barrier removed			
As-Built Meas	: 0 Quantity:	JOB Cost Estimate:	\$0.00 BSF	R: 3 Hindrance
X Coordinate:	N/A	Y Coordinate: N/A	Z Coord	inate: N/A
Implementati	on: Priority 3	Phase	Date	Status Closed
Notes:				



Field Date:	6/29/2017 Repo	t Date: 7/19/2017 Barrier #: 15L		
Facility:	Public Health (MCAH)	317 2nd St, Eureka		
Location:	Unisex Restroom 1			
Official Respo	nsible: Karen Clower	ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	THE PROPERTY OF	
Barrier Area:	Restrooms	Remediation: N/A		
Barrier Type:	WC - Rear Grab Bar Le	ngth		
Barrier Description:	Rear grab bar not at le	ast 36" long		
Code Referen	ces: CBC 11B-604.5.2 a	and 2010 ADAS 604.5.2		
As Built Description:	New grab bar 36" long			
Proposed Solution:	Barrier removed			
As-Built Meas	: 0 Quantity:	JOB Cost Estimate: \$0.00 BSR	: 3 Hindrance	
X Coordinate:	N/A	Y Coordinate: N/A Z Coordi	nate: N/A	
Implementati	on: Priority 3	Phase Date	Status Closed	
Notes:				
Field Date:	6/29/2017 Repo	t Date: 7/19/2017 Barrier #: 15M		
Facility:	Public Health (MCAH)	317 2nd St, Eureka		
Location:	Unisex Restroom 1		7060	
Official Respo	nsible: Karen Clower	ADA Coordinator	1	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1		
Barrier Area:	Restrooms	Remediation: Required		
Barrier Type:	Toilet Paper Dispenser	- Centerline		
Barrier Description:	Centerline of toilet tiss	ue dispenser not within 7" to 9" toilet seat fror	it edge	
Code Referen	ces: CBC 11B-604.7 an	d 2010 ADAS 604.7		
As Built Description:	First roll 9" from rim to	centerline. Second roll not within compliant re	each range	
Proposed Solution:	Reposition or replace t	oilet paper dispenser		
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$225.00 BSR	3 Hindrance	
X Coordinate:	N/A	Y Coordinate: N/A Z Coordi	nate: N/A	
Implementati	on: Priority 3	Phase Date	Status Open	
Notes:			OWNER	



Field Date:	5/16/2018 Repo	t Date: 9/30/2019 Barrier #: 15N		
Facility:	Public Health (MCAH)	· 317 2nd St, Eureka		
Location:	Unisex Restroom 1			
Official Respo	nsible: Karen Clower	ADA Coordinator	200	
Consent Decr	ee: Yes	Paragraph: J.2.c.iv DOJ# 6 Dwg: 1 of 1		
Barrier Area:	Restrooms	Remediation: N/A		
Barrier Type:	Seat Cover Dispensers	- Above Toilet		
Barrier Description:	Seat cover dispenser c access	ontrol point or operating mechanism not max. 40	O" AFF and toilet blocks	
Code Referen	ces: CBC 11B-603.5			
As Built Description:	Seat cover dispenser c floor space	ontrol point 28" high, mounted under rear grab b	par with required clear	
Proposed Solution:	Barrier removed			
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$0.00 BSR:	2 Recommended	
X Coordinate:	N/A	Y Coordinate: N/A Z Coordinate	ate: N/A	
Implementati	on: Priority 3	Phase Date	Status Closed	
Notes:				
Field Date:	6/29/2017 Repo	t Date: 7/19/2017 Barrier #: 16A		
Facility:	Public Health (MCAH)	· 317 2nd St, Eureka	100	
Location:	Conference Room			
Official Respo	nsible: Karen Clower	ADA Coordinator		
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1		
Barrier Area:	Signage	Remediation: Required		
Barrier Type:	Room ID Sign - No Tact	ile Information		
Barrier Description:	Room ID sign provided	for sighted people lacks tactile info for the visua	lly impaired	
Code Referen	ces: CBC 11B-216.2 an	d 2010 ADAS 216.2		
As Built Description:	No tactile information	provided where visual sign exists		
Proposed Solution:	Provide room ID sign v	vith tactile information at wall at latch side of do	or	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 BSR:	1 Necessary	
X Coordinate:	N/A	Y Coordinate: N/A Z Coordinate	ate: N/A	
Implementati	on: Priority 4	Phase Date	Status Open	
Notes:			COUNTY	



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 16B	
Facility: Public Health (MCAH) - 317 2nd St, Eureka	
Location: Conference Room	
Official Responsible: Karen Clower, ADA Coordinator	
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Doors or Gates Remediation: Required	E
Barrier Type: Door/Gate Hardware - Operation	
Barrier Description: Hardware not operable with a closed fist	
Code References: CBC 11B-404.2.7 and 2010 ADAS 404.2.7	
As Built Hardware not fist operable Description:	
Proposed Provide compliant hardware Solution:	
As-Built Meas: 2 Quantity: EACH Cost Estimate: \$600.00 BSR: 1 Necessary	1
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
Implementation: Priority 2 Phase Date Status C	Open
Notes: OWNER	
·	
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 16C	
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 16C Facility: Public Health (MCAH) - 317 2nd St, Eureka	
1 1.725/202	
Facility: Public Health (MCAH) - 317 2nd St, Eureka	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Flyer holder point of control not at max. 48" high reach	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description:	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description: Flyer holder point of control not at max. 48" high reach Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1 As Built Flyers not located within accessible reach range	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description: Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1 As Built Flyers not located within accessible reach range Proposed Move to provide accessible reach range or provide assistance	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description: Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1 As Built Description: Proposed Solution: Move to provide accessible reach range or provide assistance	
Facility: Public Health (MCAH) - 317 2nd St, Eureka Location: Conference Room Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Controls and Mechanisms Remediation: Required Barrier Type: Flyer Holder - High Reach Range Barrier Description: Code References: CBC 11B-308.2.1 and 2010 ADAS 308.2.1 As Built Description: Proposed Move to provide accessible reach range or provide assistance Solution: As-Built Meas: 1 Quantity: JOB Cost Estimate: \$0.00 BSR: 3 Hindrance	



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 16D
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Location: Conference Room
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Counters and Tables Remediation: Required
Barrier Type: Table - Knee Clearance
Barrier Knee clearance of at least 27" high, 30" wide and 19" deep not provided Description:
Code References: CBC 11B-306.3 and 2010 ADAS 306.3
As Built Description: 26-5/8" knee clearance at central tables
Proposed Solution: Provide min. 1 accessible table and 5% overall. Avoid pedestal base tables.
As-Built Meas: 1 Quantity: EACH Cost Estimate: \$450.00 BSR: 3 Hindrance
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes: COUNTY
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 16E
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Location: Conference Room
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Controls and Mechanisms Remediation: Required
Barrier Type: Operable Part - Clear Floor Space (Stored Items)
Barrier Clear floor space for person using wheelchair not provided at operable part Description:
Code References: CBC 11B-305.3 and 2010 ADAS 305.3
As Built Description: Whiteboard clear floor space blocked by chairs
Proposed Move stored items at control or mechanism Solution:
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$0.00 BSR: 1 Necessary
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 2 Phase Date Status Open
Notes: COUNTY



Field Date:	6/29/2017 Repor	t Date: 7/19/2017 Barrier #: 17A	
Facility:	Public Health (MCAH) -	317 2nd St, Eureka	
Location:	Corridor 104		
Official Respo	nsible: Karen Clower,	ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediation: Required	
Barrier Type:	Sign - 12" Circle/Triang	le at Unisex Restroom	
Barrier Description:	No 12" triangle superin	nposed on 12" circle provided on door or do	orway to unisex toilet room
Code Referen	ces: CBC 11B-703.7.2.6	3.3	
As Built Description:	Required sign not prov	ided on door or doorway	
Proposed Solution:	Provide 12" circle/trian	gle sign on door or doorway	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 B	SR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coor	rdinate: N/A
Implementati	on: Priority 2	Phase Date	Status Open
Notes:			OWNER
Field Date:	6/29/2017 Repor	t Date: 7/19/2017 Barrier #: 17B	SHIP SHIP
Facility:	Public Health (MCAH) -	317 2nd St, Eureka	
Location:	Corridor 104		
Official Respo	nsible: Karen Clower,	ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediation: Required	
Barrier Type:	Door Clear Width - 32"		
Barrier Description:	Door, sliding/folding do	oor or gate clear width is not min. 32"	
Code Referen	ces: CBC 11B-404.2.3 8	4404.3.1 and 2010 ADAS 404.2.3 & 404.3.1	
As Built Description:	29" wide		
Proposed Solution:	Replace door/gate and	frame	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$2,250.00 B.	SR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coor	rdinate: N/A
Implementati	on: Priority 2	Phase Date	Status Open
Notes:			OWNER



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 17C	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Corridor 104		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediation: Required	
Barrier Type:	Door/Gate Hardware	Operation	
Barrier Description:	Hardware not operabl	e with a closed fist	
Code Referen	ces: CBC 11B-404.2.7	and 2010 ADAS 404.2.7	
As Built Description:	Hardware not fist ope	rable	
Proposed Solution:	Provide compliant har	dware	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$300.00 BS	R: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coord	linate: N/A
Implementati	on: Priority 2	Phase Date	Status Open
Notes:			OWNER
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 17D	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Corridor 104		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediation: Required	
Barrier Type:	Maneuvering Cl - Vest	bule Doors in a Series	
Barrier Description:	Space between two co	nsecutive doors not min. 48"	
Code Referen	ces: CBC 11B-404.2.6	and 2010 ADAS 404.2.6	
As Built Description:	Corridor door and toil	et room door both swing into corridor with les	s than 12" between them
Proposed Solution:	Redesign vestibule		
As-Built Meas	: 40 Quantity:	SF Cost Estimate: \$11,000.00 BS	R: 1 Necessary
X Coordinate:		Y Coordinate: N/A Z Coord	linato: N/A
	N/A	2 Coord	linate: N/A
Implementati	, .	Phase Date	Status Open



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 18A	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Unisex Restroom 2		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediation: Required	
Barrier Type:	Sign - Braille/tactile In	formation	
Barrier Description:	No sign with Braille/Ta	actile information provided to identify restroom	
Code Referen	ces: CBC 11B-216.2 an	nd 2010 ADAS 216.2	
As Built Description:	No tactile information	at wall on latch side of door	
Proposed Solution:	Move existing sign or p	provide new sign	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$250.00 BSR	1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coordin	nate: N/A
Implementati	on: Priority 3	Phase Date	Status Open
Notes:			OWNER
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 18B	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Unisex Restroom 2		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decre	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediation: Required	
		-	
	Restrooms Sign - 12" Circle/Trians	-	way to unisex toilet room
Barrier Type: Barrier Description:	Restrooms Sign - 12" Circle/Trians	gle at Unisex Restroom mposed on 12" circle provided on door or doorv	way to unisex toilet room
Barrier Type: Barrier Description:	Restrooms Sign - 12" Circle/Triang No 12" triangle superion ces: CBC 11B-703.7.2.	gle at Unisex Restroom mposed on 12" circle provided on door or doorv	way to unisex toilet room
Barrier Type: Barrier Description: Code Referen As Built	Restrooms Sign - 12" Circle/Triang No 12" triangle superion ces: CBC 11B-703.7.2. Required sign not prov	gle at Unisex Restroom mposed on 12" circle provided on door or doorv 6.3	way to unisex toilet room
Barrier Type: Barrier Description: Code Referen As Built Description: Proposed	Restrooms Sign - 12" Circle/Triang No 12" triangle superion ces: CBC 11B-703.7.2. Required sign not provide 12" circle/trian	gle at Unisex Restroom mposed on 12" circle provided on door or doorv 6.3 vided on door or doorway ngle sign on door or doorway	way to unisex toilet room : 1 Necessary
Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution:	Restrooms Sign - 12" Circle/Triang No 12" triangle superion ces: CBC 11B-703.7.2. Required sign not provide 12" circle/tria : Quantity:	gle at Unisex Restroom mposed on 12" circle provided on door or doorv 6.3 vided on door or doorway ngle sign on door or doorway EACH Cost Estimate: \$250.00 BSR	
Barrier Type: Barrier Description: Code Referen As Built Description: Proposed Solution: As-Built Meas	Restrooms Sign - 12" Circle/Triang No 12" triangle superion ces: CBC 11B-703.7.2. Required sign not prov Provide 12" circle/trian : 1 Quantity: N/A	gle at Unisex Restroom mposed on 12" circle provided on door or doorv 6.3 vided on door or doorway ngle sign on door or doorway EACH Cost Estimate: \$250.00 BSR	: 1 Necessary



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 18C	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Unisex Restroom 2		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediation: Required	
Barrier Type:	Door Clear Width - 32		
Barrier Description:	Door, sliding/folding d	oor or gate clear width is not min. 32"	
Code Referen	ces: CBC 11B-404.2.3	& 404.3.1 and 2010 ADAS 404.2.3 & 404.3.1	
As Built Description:	31" wide		
Proposed Solution:	Replace door/gate and	d frame	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$2,250.00 BSF	R: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coord	inate: N/A
Implementati	on: Priority 3	Phase Date	Status Open
Notes:			OWNER
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 18D	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Unisex Restroom 2		0
Official Respo	nsible: Karen Clower	, ADA Coordinator	No. of the last of
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Doors or Gates	Remediation: Required	
Barrier Type:	Door/Gate Hardware -	Operation	
Barrier Description:	Hardware not operabl	e with a closed fist	
Code Referen	ces: CBC 11B-404.2.7	and 2010 ADAS 404.2.7	
As Built Description:	Hardware not fist ope	rable	
Proposed Solution:	Provide compliant har	dware	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$300.00 BSF	R: 1 Necessary
	. II Quantity:		·
X Coordinate:		Y Coordinate: N/A Z Coord	inate: N/A
	N/A	Y Coordinate: N/A Z Coord Phase Date	inate: N/A Status Open



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 18E	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Unisex Restroom 2		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of	1
Barrier Area:	Doors or Gates	Remediation: Required	
Barrier Type:	Maneuvering Cl - Int F	ront App/Pull 18"	
Barrier Description:	Door/Gate at pull side	lacks min. 18" beyond latch side of door	
Code Referen	ces: CBC Figure 11B-4	04.2.4.1 and 2010 ADAS 404.2.4.1	
As Built Description:	11" strike edge cleara	nce at exit side of door	
Proposed Solution:	Install automatic door	opening device or remodel toilet room to	provide wheelchair access
As-Built Meas	Quantity:	EACH Cost Estimate: \$5,000.00	BSR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z C	Coordinate: N/A
Implementati	on: Priority 3	Phase Date	Status Open
Notes:			OWNER
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017 Barrier #: 18F	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka	
Location:	Unisex Restroom 2		
Official Respo	nsible: Karen Clower	, ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of	1
Barrier Area:	Doors or Gates	Remediation: Required	
Barrier Type:	Maneuvering Cl - Store	ed Items	
Barrier Description:	Door/Gate lacks requi	red maneuvering clearance	
Code Referen	ces: CBC Figure 11B-4	04.2.4.1 and 2010 ADAS 404.2.4.1	
As Built Description:	Trash bin blocks strike	edge clearance at exit side	
Proposed Solution:	Relocate items		
As-Built Meas	: 0 Quantity:	EACH Cost Estimate: \$0.00	BSR: 1 Necessary
X Coordinate:	NI/A	Y Coordinate: N/A Z C	Coordinate: N/A
	IN/A		
Implementati	, .	Phase Date	Status Open



Field Date:	6/29/2017 Repor	t Date: 7/19/2017 Barrier #: 18G	A
Facility:	Public Health (MCAH)	317 2nd St, Eureka	
Location:	Unisex Restroom 2		
Official Respo	nsible: Karen Clower,	ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	
Barrier Area:	Restrooms	Remediation: Required	
Barrier Type:	Lavatory - Knee Cleara	nce	
Barrier Description:	Lavatory bottom apror	n/edge not max 29" reducing to 27" at 8" bac	k from edge
Code Referen	ces: CBC 11B-606.2 an	d 2010 ADAS 606.2	
As Built Description:	Cabinet blocks knee clo	earance	
Proposed Solution:	Remodel toilet room to	provide wheelchair access	
As-Built Meas	: 1 Quantity:	JOB Cost Estimate: \$450.00 B	SR: 1 Necessary
X Coordinate:	N/A	Y Coordinate: N/A Z Coor	rdinate: N/A
Implementati	on: Priority 3	Phase Date	Status Open
Notes:			OWNER
Field Date:	6/29/2017 Repor	t Date: 7/19/2017 Barrier #: 18H	
Facility:	Public Health (MCAH)	317 2nd St, Eureka	
Location:	Unisex Restroom 2		
Official Respo	nsible: Karen Clower,	ADA Coordinator	
Consent Decr	ee: No	Paragraph: M.51 Dwg: 1 of 1	- Taken
Barrier Area:	Restrooms	Remediation: Required	
Barrier Type:	Dispensers - Control Po	pint	
Barrier Description:	Dispenser control poin	t or operating mechanism not max. 40" AFF	
Code Referen	ces: CBC 11B-603.5		
As Built Description:	48" high		
Proposed Solution:	Replace or remount di	spenser	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate: \$125.00 B.	SR: 2 Recommended
X Coordinate:	N/A	Y Coordinate: N/A Z Coor	dinate: N/A
Implementati	on: Priority 3	Phase Date	Status Open
Notes:			



Field Date:	6/29/2017 Repo	rt Date: 7/19/2017	Barrier #:	181	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka			
Location:	Unisex Restroom 2				
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1	l of 1	an united
Barrier Area:	Restrooms	Remediat	ion: Require	ed	
Barrier Type:	Mirror - Bottom Edge				
Barrier Description:	Mirror at lavatory/cou	ntertop not max. 40" AFF	at edge of re	eflecting surface	
Code Referen	ces: CBC 11B-603.3 an	d 2010 ADAS 603.3			
As Built Description:	50" high				
Proposed Solution:	Provide min. one acce	ssible mirror at lavatory o	r dressing co	unter	
As-Built Meas	: 1 Quantity:	EACH Cost Estimate:	\$375.00	BSR: 3 Hindrance	
X Coordinate:	N/A	Y Coordinate: N/A		Z Coordinate: N/A	
Implementati	on: Priority 3	Phase	Date	Status Open	
Notes:				OWNER	
Field Date:	6/29/2017 Repo	rt Date: 7/19/2017	Barrier #:	18J	
Facility:	Public Health (MCAH)	- 317 2nd St, Eureka			-
Location:	Unisex Restroom 2				C
Official Respo	nsible: Karen Clower	, ADA Coordinator			
Consent Decre	ee: No	Paragraph: M.51	Dwg: 1	L of 1	
Barrier Area:	Restrooms	Remediat	ion: Require	ed	
Barrier Type:	Toilet Paper Dispenser	- Centerline			
Barrier Description:	Centerline of toilet tiss	sue dispenser not within 7	" to 9" toilet	seat front edge	
Code Referen	ces: CBC 11B-604.7 an	d 2010 ADAS 604.7			
As Built Description:	16" from rim to center	line			
Proposed Solution:	Reposition or replace	toilet paper dispenser			
As-Built Meas	Quantity:	EACH Cost Estimate:	\$225.00	BSR: 3 Hindrance	
X Coordinate:	N/A	Y Coordinate: N/A		Z Coordinate: N/A	
Implementati	on: Priority 3	Phase	Date	Status Open	
Notes:				OWNER	



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 18K
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Location: Unisex Restroom 2
Official Responsible: Karen Clower, ADA Coordinator
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area: Restrooms Remediation: Required
Barrier Type: Maneuvering Clearance - 60" Circle
Barrier No 60" turning circle provided in toilet facility (min. 27" high above floor) Description:
Code References: CBC 11B-304.3.1, 11B-603.2.1 and 2010 ADAS 603.2.1
As Built 37" between toilet rim and janitor's basin Description:
Proposed Remodel toilet room Solution:
As-Built Meas: 80 Quantity: SF Cost Estimate: \$46,000.00 BSR: 2 Recommended
X Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A
Implementation: Priority 3 Phase Date Status Open
Notes: OWNER
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 18L
Facility: Public Health (MCAH) - 317 2nd St, Eureka
Public Health (MCAH) - 317 2nd St, Eureka Location: Unisex Restroom 2
Location: Unisex Restroom 2
Location: Unisex Restroom 2 Official Responsible: Karen Clower, ADA Coordinator
Location: Unisex Restroom 2 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1
Location: Unisex Restroom 2 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required
Location: Unisex Restroom 2 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Seat Cover Dispensers - Above Toilet Seat cover dispenser control point or operating mechanism not max. 40" AFF and toilet blocks
Location: Unisex Restroom 2 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Seat Cover Dispensers - Above Toilet Barrier Description: Seat cover dispenser control point or operating mechanism not max. 40" AFF and toilet blocks access
Location: Unisex Restroom 2 Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Seat Cover Dispensers - Above Toilet Barrier Description: Seat cover dispenser control point or operating mechanism not max. 40" AFF and toilet blocks access Code References: CBC 11B-603.5 As Built Seat cover control point higher than 40" and clear floor space at dispenser is blocked by toilet
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Barrier Type: Seat Cover Dispensers - Above Toilet Barrier Description: Seat cover dispenser control point or operating mechanism not max. 40" AFF and toilet blocks access Code References: CBC 11B-603.5 As Built Description: Replace or remount dispenser
Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Remediation: Required Barrier Type: Seat Cover Dispensers - Above Toilet Barrier Description: Seat cover dispenser control point or operating mechanism not max. 40" AFF and toilet blocks access Code References: CBC 11B-603.5 As Built Description: Seat cover control point higher than 40" and clear floor space at dispenser is blocked by toilet Description: Replace or remount dispenser
Official Responsible: Karen Clower, ADA Coordinator Consent Decree: No Paragraph: M.51 Dwg: 1 of 1 Barrier Area: Restrooms Barrier Type: Seat Cover Dispensers - Above Toilet Barrier Description: Seat cover dispenser control point or operating mechanism not max. 40" AFF and toilet blocks access Code References: CBC 11B-603.5 As Built Description: Seat cover control point higher than 40" and clear floor space at dispenser is blocked by toilet Description: Replace or remount dispenser Replace or remount dispenser As-Built Meas: 1 Quantity: EACH Cost Estimate: \$125.00 BSR: 2 Recommended



Field Date:	6/29/2017 Report Date: 7/19/2017 Barrier #: 18M
Facility:	Public Health (MCAH) - 317 2nd St, Eureka
Location:	Unisex Restroom 2
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Restrooms Remediation: Required
Barrier Type:	WC - Flush Controls Location
Barrier Description:	Flush controls does not point to wide side of stall or compartment
Code Referen	ces: CBC 11B-604.6 and 2010 ADAS 604.6
As Built Description:	Handle points towards wall or partition
Proposed Solution:	Provide min. one accessible water closet
As-Built Meas	: 1 Quantity: JOB Cost Estimate: \$850.00 BSR: 1 Necessary
X Coordinate:	N/A Y Coordinate: N/A Z Coordinate: N/A
Implementati	on: Priority 3 Phase Date Status Open
Notes:	OWNER
Field Date:	6/29/2017 Report Date: 7/19/2017 Barrier #: 18N
Facility:	Public Health (MCAH) - 317 2nd St, Eureka
Location:	Unisex Restroom 2
Official Respo	nsible: Karen Clower, ADA Coordinator
Consent Decre	ee: No Paragraph: M.51 Dwg: 1 of 1
Barrier Area:	Restrooms Remediation: Required
Barrier Type:	WC - No Grab Bars
Barrier Type: Barrier Description:	
Barrier Description:	WC - No Grab Bars
Barrier Description:	WC - No Grab Bars Grab bars not provided at the water closet
Barrier Description: Code Reference As Built	WC - No Grab Bars Grab bars not provided at the water closet ces: CBC 11B-604.5 and 2010 ADAS 604.5
Barrier Description: Code Referen As Built Description: Proposed	WC - No Grab Bars Grab bars not provided at the water closet ces: CBC 11B-604.5 and 2010 ADAS 604.5 Grab bars not provided Provide compliant grab bars with required reinforcement
Barrier Description: Code Reference As Built Description: Proposed Solution:	WC - No Grab Bars Grab bars not provided at the water closet ces: CBC 11B-604.5 and 2010 ADAS 604.5 Grab bars not provided Provide compliant grab bars with required reinforcement : 2 Quantity: JOB Cost Estimate: \$2,900.00 BSR: 1 Necessary
Barrier Description: Code Reference As Built Description: Proposed Solution: As-Built Meas	WC - No Grab Bars Grab bars not provided at the water closet ces: CBC 11B-604.5 and 2010 ADAS 604.5 Grab bars not provided Provide compliant grab bars with required reinforcement : 2 Quantity: JOB Cost Estimate: \$2,900.00 BSR: 1 Necessary N/A Y Coordinate: N/A Z Coordinate: N/A



Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 180	9
Facility: Public Health (MCAH) - 317 2nd St, Eureka	
Location: Unisex Restroom 2	- 10
Official Responsible: Karen Clower, ADA Coordinator	1
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Restrooms Remediation: Required	
Barrier Type: WC - Seat Height	
Water closet + seat not between 17" to 19" high Description:	
Code References: CBC 11B-604.4 and 2010 ADAS 604.4	
As Built 15-1/2" high Description:	
Proposed Provide min. one accessible water closet Solution:	
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$850.00 BSR: 2 Recommended	
Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
mplementation: Priority 3 Phase Date Status Open	
Notes: OWNER	
Field Date: 6/29/2017 Report Date: 7/19/2017 Barrier #: 18P	The same
Facility: Public Health (MCAH) - 317 2nd St, Eureka	
Location: Unisex Restroom 2	1
Official Responsible: Karen Clower, ADA Coordinator	16
Consent Decree: No Paragraph: M.51 Dwg: 1 of 1	
Barrier Area: Restrooms Remediation: Required	
Barrier Type: WC - Centerline	
Water closet centerline not between 17" and 18" measured on center from wall Description:	
Code References: CBC 11B-604.2 (2010 ADAS 604.2 less stringent)	
As Built 14-1/2" OC Description:	
Proposed Provide min. one accessible water closet Solution:	
As-Built Meas: 1 Quantity: JOB Cost Estimate: \$850.00 BSR: 3 Hindrance	
Coordinate: N/A Y Coordinate: N/A Z Coordinate: N/A	
mplementation: Priority 3 Phase Date Status Open	
Notes: OWNER	

COST ESTIMATES



SUMMARY REPORT

Cost Estimate Total	\$117,270.00		
Cost Estimate - Priority 1:	\$25,645.00	% of Total Cost Estimate:	21.87%
Cost Estimate - Priority 2:	\$27,525.00	% of Total Cost Estimate:	23.47%
Cost Estimate - Priority 3:	\$61,600.00	% of Total Cost Estimate:	52.53%
Cost Estimate - Priority 4:	\$2,500.00	% of Total Cost Estimate:	2.13%

