

Certified Access Specialist (CASp) Assessment dated June 27, 2018.

Barriers to be removed by Lessor

Item 1.9, parking Space Width – Car

Item 1.10, Parking Space Width – Van

Item 1.11, Van Access Aisle

Item 1.12, Car & Van Access Parking

Item 1.13, Car Access Aisles

Item 1.20 – Marking

Item 1.21 – Tow-away Sign

Item 3/19B – Entrance Signs

Item 3.20B – Directions to Accessible Entrance

Item 7.2 – Slope

Item 7.6 – Clear Width

Item 7.13 – Landings with Doors

Item 7.17 – Handrails

Item 7.21 – Handrail Extension

Item 7.27 – Other

Item 10.1 – Entrances Serving Site Arrival Points

Item 10.2 – Entrance Sign

Item 10.8 – Kick Plate

Item 10.9 – Door Threshold

Item 12.29A – Alarms

Item 16.1 – Toilet Rooms

Item 16.3 – Unisex Toilet Rooms

Item 16.6 – Entry Doors

Item 16.11 – Door Maneuvering Space

Item 16.12 – Other Door Requirements

Item 16.13 – Identification Symbols

Item 16.27 – Maneuvering Space

Item 16.29 – Maneuvering Space

Item 16.45 – Toilet Paper Dispenser

Item 16.48 – Seat Cover Dispenser

Item 16.51 – Grab Bar Wall Clearance

Item 16.52 – Grab Bar Clearance

Item 16.55 – Rear Grab Bar

Item 16.63 – Lavatories

Item 16.64 – Lavatories Rim Height

Item 16.69 – Side Clearance at Lavatory

Item 16.70 – Pipe Insulation at Lavatory

Item 16.75 – Coat Hook

Item 16.76 – Dispensers Operating Height