

Exhibit C

Open ADA Barriers Social Services Branch 808 E St
Accessibility Compliance Assessment Report
by Jensen Hughes' inspection 9/16/2021

Barrier #	Description	Location	Responsibility
5B	Push Plates	Lobby Door Exterior	Landlord
5B	Push Plates	Lobby Door Interior	Landlord
8K	Door Pressure	Corridor 100 F	Landlord
8L	Door Threshold	Corridor 100 F	Landlord