| Photo | Corrective Action Required | | | | |
|----------------------------|--|--|--|--|--|
| 1 | Ensure that any leaking water tanks/lines are fixed immediately. | | | | |
| 2 | The far-left greenhouse was installed in 2021. | | | | |
| | Remove this greenhouse and submit revised Site Plan. | | | | |
| 3 | Treat slash pile | | | | |
| 4 | Exposed electrical. Applicant and agent were previously notified of the need to fix electrical issues during December 18, 2020, inspection. Streamside Management Area not shown on site plan. Submit revised Site Plan showing SMA. | | | | |
| | | | | | |
| 5, 6, 7 | Separate Solid Waste. Place nutrients in secondary containment. Identified during 2020 inspection. | | | | |
| 8 | Dispose of trash at a waste management facility. Identified during 2020 inspection. | | | | |
| 9 | Separate solid waste. | | | | |
| 10 | Exposed car battery, gasoline containers, etc. Place in secondary containment unit and separate solid waste. | | | | |
| 11-23 | Remove Lighting from Outdoor Greenhouses. Applicant and agent were notified of the need to remove lighting at Site Inspection in December 2020. | | | | |
| 24 | "GH 13", no dimensions or use labeled on site plan. (100 x 20) "GH 12" is shown on site plan but has been removed. Revise site plan to include dimensions, use, and show removal of greenhouse 12. | | | | |
| 25-29 | Remove lights from outdoor greenhouses. Applicant and agent were notified of the need to do so during December 2020 site inspection. | | | | |
| 30 | Uncontained soil pile with dispersed perlite. Soil must be better contained with fiber rolls or other erosion control measures. | | | | |
| 31 | Water tank in the SMA. Labeled as domestic, no action required. | | | | |
| 32 | Remove lights from outdoor greenhouse. | | | | |
| 33 | Remove lights from outdoor greenhouse. | | | | |
| 34 | Area labeled as "GH 11" and "GH 10" Inaccurately labeled on site plan as being a combined area of 520 SF. Actual size of area is approximately 1600 SF. Decommission this area. Exceeds the immature plant area allotted. It is unclear how the applicant covers the lights in this area. Submit revised Site Plan showing this area decommissioned. | | | | |
| 35 | Remove GH 6, GH 7, and GH 8 as shown on site plan. Installed in 2020 without county review or approval. Submit revised Site Plan. | | | | |
| Immature | "GH 13"= 2,000 SF | | | | |
| Plant Area | "GH 11" and "GH 10" = 1600 SF | | | | |
| Totals | "GH 8"= 2,850 | | | | |
| | Garage= 780 Total= 7,230 SF | | | | |
| Mixed | "GH 1"= 1620 | | | | |
| Light | "GH 2"= 1800 | | | | |
| Cultivation Area Totals | "GH 8" dimensions not labeled on site plan= (100 x 20) 2,000 SF "GH 9"= 1440 SF | | | | |
| | Total ML Area= 6860 square feet | | | | |



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34




Photo 35